START

JUN 2 2 1994

ENGINEERING DATA TRANSMITTAL

Page 1 of __i

1. EDT

600222

2. To: (Receiving Organization) Distribution					3. From: (Originating Organization) Environmental Restoration Field Sampling			4. Related EDT No.: N/A				
5. Proj./Prog./Dept./Div.: 200 West Area Carbon Tetrachloride ERA					6. Cog. Engr.: J. D. Fancher			7. Purchase Order No.: N/A				
8. Ori	ginator	Remarks:			<u> </u>			9. Equip./	Componen	t No.:		
For	rele	ase and	distribu	ution.					N/	Α		
		٠				1		10. System	n/Bldg./f N/	•		
11. Re	eceiver	Remarks:			JUN 1994 CONTROL RECEIVED CONTROL CONT			12. Major Assm. Dwg. No.: N/A				
					RECEIVED 6			13. Permit/Permit Application No.: N/A				
						1617 13 TO SECULO !!		14. Requír	ed Respo		:	
15.			<u> </u>	DA	TA TRANSMITTE			(F)	(G)	(H)	(1)	
(A) Item No.	(B)	Document/Dr	ewing No.	(C) Sheet No.	(D) Rev. No.	1 ' '	escription of Data	Impact Level	Reason for Trans- mittal	Origi- nator Dispo- sition	Receiv- er Dispo- sition	
1 WHC-SD-EN-TI-265 N/A			0	Carbon Tet ERA Soil-G Monitoring	NΑ	1	1					
16.						KEY						
1111/201-0000 (1)				n for Transmittal (G)			Disposition (H) & (I)					
1 11111 0:107				st-Review	, , ,							
(G)	(H)	17.				SIGNATURE/DISTRIBUTION (See Impact Level for required signatures)						
Rea- Disp. (J) Name (K) Signature			(L) Date (M) MSIN (J) Name (K) Signat			ture (L) Date (M) MSIN			Disp.			

(G)	(H)	17.		(Sec		E/DISTRIBUTION for required signatures)			(G)	(H)
Rea- son	Disp.	(J) Name	(K) Signature	(L) Date	(M) MSIN	(J) Name	(K) Signatur	e (L) Date	(M) MSIN	Rea- son	. Disp.
1)	Cog.Eng. J.D.	Fancher (10.)	Dotum	13-0 M3-0	,					
1	l.	Cog. Mgr. W.S	. Thompson %	Sthor	nper 13-0	5				<u> </u>	
1	1	Proj. Sci. V.	J. Rohay	Chay	6/17/946-0	6				L	
										-	
							<u> </u>		. •	 	
17.8	ancher Turn ure of ED	M C) 17 GH	G. C. Henckel Authorized Representation Receiving Or			20. W. S. Thomoson The Sometime Cognizant/Project Engineer's Manager	Coln Ay	Ltr. N [] Approve		· •	i)

INSTRUCTIONS FOR COMPLETION OF THE ENGINEERING DATA TRANSMITTAL

			(USE BLACK INK OR TYPE)
BLOCK	TITLE		
(1)*	EDT	•	Pre-essigned EDT number.
(2)	To: (Receiving Organization)	•	Enter the individual's name, title of the organization, or entity (e.g., Distribution) that the EDT is being transmitted to.
(3)	From: (Originating Organization)	•	Enter the title of the organization originating and transmitting the EDT.
·(4) - · ·	Related EDT No.	•	Enter EDT numbers which relate to the data being transmitted.
(5) *	Proj./Prog./Dept./Div.	•	Enter the Project/Program/Department/Division title or Project/Program acronym or Project Number, Work Order Number or Organization Code.
(6)*	Cognizant Engineer	●_	Enter the name of the individual identified as being responsible for coordinating disposition of the EDT.
(7)	Purchase Order No.	•	Enter related Purchase Order (P.O.) Number, if available.
(8) *	Originator Remarks	•	Enter special or additional comments concerning transmittal, or "Key" retrieval words may be entered.
(9)	Equipment/Component No.	•	Enter equipment/component number of affected item, if appropriate.
(10)	System/Bldg./Facility	•	Enter appropriate system, building or facility number, if appropriate.
(11)	Receiver Remarks	•	Enter special or additional comments concerning transmittal.
(12)	Major Assm. Dwg. No.	•	Enter applicable drawing number of major assembly, if appropriate.
(13)	Permit/Permit Application No.	•	Enter applicable permit or permit application number, if appropriate.
(14)	Required Response Date	•	Enter the date a response is required from individuals identified in Block 17 (Signature/Distribution).
(15)*	Data Transmitted		
	(A)* Item Number	•	Enter sequential number, beginning with 1, of the information listed on EDT.
	(B)* Document/Drawing No.	•	Enter the unique identification number assigned to the document or drawing being transmitted.
	(C) * Sheet No.	•	Enter the sheet number of the information being transmitted. If no sheet number, leave blank.
	(D)* Rev. No.	•	Enter the revision number of the information being transmitted. If no revision number, leave blank.
1	(E) Title or Description of Data Transmitted	•	Enter the title of the document or drawing or a brief description of the subject if no title is identified.
	(F) * Impact Level	•	Enter the appropriate impact Level (Block 15). Also, indicate the appropriate approvals for each item listed, i.e., SQ, ESQ, etc. Use NA for non-engineering documents.
	(G) Reason for Transmittel	•	Enter the appropriate code to identify the purpose of the data transmittal (see Block 16).
	(H) Originator Disposition	•	Enter the appropriate disposition code (see Block 16).
	(I) Receiver Disposition	•	Enter the appropriate disposition code (see Block 16).
(16) : ****	Key	• 8	Number codes used in completion of Blocks 15 (G), (H), and (I), and 17 (G), (H) (Signature/Distribution).
(17)	Signature/Distribution		
	(G) Reason	•	Enter the code of the reason for transmittal (Block 16).
	(H) Disposition	•	Enter the code for the disposition (Block 16).
	(J) Name	•	Enter the signature of the individual completing the Disposition 17 (H) and the Transmittal.
	(K) * Signature	•	Obtain appropriate signature(s).
	(L) * Date	•	Enter date signature is obtained.
	(M) • MSIN	. •	Enter MSIN. Note: If Distribution Sheet is used, show entire distribution (including that indicated on Page 1 of the EDT) on the Distribution Sheet.
(18)	Signature of EDT Originator	•	Enter the signature and date of the individual originating the EDT (entered prior to transmittal to Receiving Organization). If the EDT originator is the cognizant engineer, sign both Blocks 17 and 18.
(19)	Authorized Representative for Receiving Organization	•	Enter the signature and date of the individual identified by the Receiving Organization as authorized to approve disposition of the EDT and acceptance of the data transmitted, as applicable.
(20)*	Cognizant Manager	•	Enter the signature and date of the cognizant manager. (This signature is authorization for release.)
(21)*	_DOE Approval .	•	Enter DOE approval (if required) by letter number and indicate DOE action.

^{*}Asterisk denote the required minimum items check by Configuration Documentation prior to release; these are the minimum release requirements.

Date Received:		INFORMATI	ON R	ELEASE	REQUI	EST	•	Reference: WHC-CM-3-4
100/1/00		Complete fo	rall 1	Types of				
Pu	rpose				ID Numi	ber (include rev		e, etc.)
[] Speech or Presentation	, l	[X] Reference			WHC-S	SD-EN-TI-265	о, кеv. O	
	one		n Disserta	ation	List a	ttachments.		
[] Summary suff	ix)	[] Manual			N/A			
[] Abstract		[] Brochure	s/Flier s/Databas	.	IV/A			
[] Visual Aid [[] Speakers Bureau			ed Docum		Date R	elease Required		
[] Poster Session	1	[] Other						
[] Videotape				•	<u> </u>	l time i energia de		
Title Carbon Tetrachloric	de ERA	A Soll-Gas	Basel	ıne		Unclassified (UC- 630	Lategory	Impact Level N/A
Monitoring	E 1/ 3			Informatio	n received	from others in confid	dence such as r	proprietary data
New or novel (patentable) subject matter? If "Yes", has disclosure been submitted by "	[X] NHCoro		.			inventions?	oonee, oaen ee p	nophotoly duta,
No Yes Disclosure No(s).		chor company.		[X] No	[] Y	es (Identify)		
Copyrights? [X] No [] Yes				Trademarl				
If "Yes", has written permission been grante	ad?	•		[X] No	[] Y	es (Identify)		
[] No [] Yes (Attach Permission)		<u> </u>						
		Complete for	r Speec					
Title of Conference or Meeting				Group o	r Society	Sponsoring		
N/A					 			
Date(s) of Conference or Meeting	City/	State					[] v	Г1 на
bate(s) of conference of Meeting	""	o tace			•	ngs be published?	[] Yes [] Yes	[] No
7:01-06 (00-00)	<u> </u>			v	III materiai i	be handed out?	F1 169	f1 "0
Title of Journal						•		
		CHECKL	IST FOR	SIGNATO	RIES			
Review Required per WHC-CM-3-4	Yes	<u>No</u> R		- Signa me (print	_	icates Approval Sign	nature	<u>Date</u>
Classification/Unclassified Controlled	ſΊ	[X]						
Nuclear Information Patent - General Counsel	[] ^ [v			1 10		C 0 2.4	4/-0104	
Legal - General Counsel	λ] γγ Σ- [X					Crym dotal		
Applied Technology/Export Controlled	717/TX] X 🚾	ir tra	Anish AV	y Ook	mem fresh "	11 70/47	
Information or International Program	[]	[X]						
WHC Program/Project	٢X] [] 	1.D. [Downey	· []	J. 1)		6/2/74
Communications	[]	·				- 1		
RL Program/Project	[X		G.I. (Goldbei	rg /	t. Har	$\overline{}$	6/21/94
Publication Services	[X	- :: -		Kowals	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	bus Chans	2	6-17-94
Other Program/Project	[]	- <u></u>	1		· · · · · · · · · · · · · · · · · · ·			- (
Information conforms to all appli			The abo	ve inform	mation is	certified to be	e correct.	
THO MACTOR CONTORMS to act apper	Ye		1			ELEASE ADMINIST		/AL STAMP
References Available to Intended Audience	[X	-		p is require		lease. Release is cor	ntingent upon re	solution of
Transmit to DOE-HQ/Office of Scientific and Technical Information				·		O FOA		
	_ [X				٤	O STICE.	A. A.	
Author/Requestor (Printed/Signate	re)	Date , ,			4	σ ο σ σ σ σ σ σ σ σ σ σ σ σ σ σ σ σ σ σ	10	
J. D. Fancher J. J. Tum	hn	417/94					Sen and the second seco	
Intended Audience					**************************************		at I	
[] Internal [] Sponsor	[X] E	xternal				6122	7	
							Acces 1	
Responsible Manager (Printed/Sign	ia rui e	Date						
G. C. Henckel	XIX-	4/17/94	Date	Cancell	ed	Dat	e Disapprove	d

THIS PAGE INTENTIONALLY LEFT BLANK

SUPPORTING DOCUMENT	1. то	tal Pages		
2. Title Carbon Tetrachloride ERA Soil-Gas Baseline Monitoring	3. Number WHC-SD-EN-TI-265	4. Rev No.		
5. Key Words	6. Author			
Carbon Tetrachloride, Soil-Gas, Volatile Organic Compounds	Name: J. D. Fancher Signature Organization/Charge Code 8B410/PU2BC			
APPROVED FOR				
PUBLIC RELEASE				
7. Abstract 6/22/9410. Do	lis.			

This report contains observations of the patterns and trends associated with data obtained during soil-gas monitoring at the 200 West Area Carbon Tetrachloride

Expedited Response Action (ERA). Monitoring performed since late 1991 includes monitoring soil-gas probes and wellheads for volatile organic compounds (VOCs). This report reflects monitoring data collected from December 1991 through December 1993.

Fancher, J. D., 1994, Carbon Tetrachloride Soil-Gas Baseline Monitoring, WHC-SE-EN-TI-265, Rev. O, Westinghouse Hanford Company, Richland, Washington.

8. PRPOSE AND USE OF DOCUMENT - This document was prepared for se within the U.S. Department of therety and its contractors. It is to be seed only to perform direct, or integrate work under U.S. Dispartment of Energy contracts. This document is not approved for public release until reviewed.

PATENT STARS - The document copy, since it is cansmitted in advance of pat proclearance, is made available in continuence solely for use in reformance of work under contracts with the U.S. Department of Energy. This document is not to be published nor its content otherwise disseminated or used for purposes other than specific above before patent approval for such release or use has been cured, upon request, from the Patent Counsel, U.S. Department of othersy Field Office, Richland, U.S.

DISCLAIMER - This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

10. RELEASE STAMP

OFFICIAL RELEASE
BY WHC

DATE JUN 2 2 1994

35

Station 21

9. Impact Level NA

THIS PAGE INTENTIONALLY LEFT BLANK

CONTENTS

1.0	INTRODUCTION	3 3 3 4
2.0	SOIL-GAS BASELINE MONITORING 2.1 PURPOSE 2.2 SCOPE 2.2.1 ROUTINE BASELINE MONITORING 2.2.2 NONROUTINE FARFIELD MONITORING 2.2.3 SEALED WELL TESTING 2.3 SAMPLING METHODS 2.4 MONITORING INSTRUMENTS 2.5 SAMPLING DATA	2 4 5 11 11 13 13
3.0	ROUTINE BASELINE MONITORING DATA DISCUSSION 3.1 WELLHEAD SAMPLING DATA 3.2 SHALLOW SOIL-GAS PROBE DATA 3.3 DEEP SOIL-GAS PROBE DATA 3.4 MULTI-LEVEL SOIL-GAS POINTS 3.5 216-Z-12 CRIB 3.6 FARFIELD MONITORING	14 14 15 15 15 16
4.0	COMPARISON OF SAMPLING DATA SETS	18 18 25 25 25 25 31
5.0	NONROUTINE FARFIELD MONITORING	34
6.0	SEALED WELL TESTS	36
7:0-	CONCLUSIONS	4]
8.0	REFERENCES	42
	APPENDICES	
A B C	BASELINE MONITORING STATISTICS - DECEMBER 1991 THROUGH DECEMBER 1993 WELL CONSTRUCTION DATA CALCULATIONS USED TO DERIVE VADOSE OPEN AREA NONROUTINE FARFIELD MONITORING DATA	

FIGURES

2-1	Baseline Monitoring Locations Near the ERA Site	6
2=2	Farfield Baseline Monitoring Locations	7
2-3	Multi-level Soil-Gas Point Locations	۶
2-4	Typical Well Construction Diagram	C
2-5	Typical Shallow and Deep Soil-Gas Probe Installations	10
2-6	Typical Multi-Level Spil-Gas Point Installation	10
3-1	Maximum VOC Concentrations Detected at Routine Farfield Monitoring Wells .	17
4-1	Maximum VOC Concentrations over time at Well 299-W15-82	ĵ¢
4-2	Contours of Maximum VOC Concentrations in Wells Screened Above Caliche	21
4-3	Contours of Maximum VOC Concentrations in Wells Screened Below Caliche	22
4-4	Maximum Wellhead VOC Concentrations	23
4-5	Maximum VOC Concentrations Above and Below Caliche at Well 299-W15-216.	24
4-6	Contours of Maximum VOC Concentrations in Shallow Soil-Gas Probes	26
4-7	Maximum VOC Concentrations over time at Shallow Soil-Gas Probe SG N-9	27
4-8	Shallow Soil-Gas Probe Detections	28
4-9	Maximum VOC Concentrations over time at Deep Soil-Gas Probe CPT-15-6	29
4-10	Maximum VOC Concentrations over time at Multi-Level Soil-Gas Probe CPT4F .	30
4-11	VOC Concentrations at Well 299-W15-216 and Deep Soil-Gas Probe SG 15-6	32
4-12	VOC Concentrations at Well 299-W15-216, Deep Soil-Gas Probe SG 15-6,	J.
	and Shallow Soil-Gas Probe SG 94-02	33
5-1	Nonroutine Farfield Monitoring Wells and VOC Detections	34
6-1	Sealed Well Test April 13, 1993	36
6-2	Sealed Well Test August 3, 1993	37
6-3	Sealed Well Test December 3, 1993	38
6-4	Sealed Well Test December 28, 1993	30
		ر د
	TABLES	
2-1	Routine Baseline Monitoring Locations	_
3-1	Routine Baseline Monitoring Locations	10
5-1	Nonroutine Farfield VOC Detections	3 E
- I	noniousine furficia too betections	აა

Carbon Tetrachloride Soil-Gas Baseline Monitoring

EXECUTIVE SUMMARY

From December 1991 through December 1993, Westinghouse Hanford Company performed routine baseline monitoring of selected wells and soil-gas points twice weekly in the 200 West Area of the Hanford Site. This work supported the Carbon Tetrachloride Expedited Response Action (ERA) and provided a solid baseline of volatile organic compound (VOC) concentrations in wells and in the subsurface at the ERA site. As site remediation continues, comparisons to this baseline can be one means of measuring the success of carbon tetrachloride vapor extraction.

Wellheads and soil-gas points were analyzed using a photoionization detector. Results of the monitoring indicate concentrations of VOCs vary over time and space. Wellhead concentration results spanned a much greater range than shallow soil-gas probe concentrations.

VOC concentrations in wellheads and deep soil-gas probes ranged from less than detectable to exceeding the photoionization detector's capacity of 10,000 ppmv. Shallow soil-gas concentrations ranged from less than detectable to over 100 ppmv.

Concentrations of VOCs were highest at the 216-Z-9 Trench, where levels exceeded 10,000 ppmv at two wells, and at one deep soil-gas probe. Maximum concentrations detected at the 216-Z-1A Tile Field and the 216-Z-18 Crib wells were 1,532 and 442 ppmv, respectively.

Vertical variations in VOCs in wells indicate concentrations are highest in wells with subsurface open areas (perforations or screen) above a locally semi-confining (caliche) layer. In wells with subsurface openings below the caliche layer, VOC concentrations tended to be higher in wells screened just above groundwater.

Distance between a well and the carbon tetrachloride waste disposal area also influences levels of VOCs detected in wellheads. Wells located very near waste disposal sites generally have higher concentrations than wells farther away.

Two seasonal trends have emerged from the data set: VOC concentrations in wellheads and deep soil-gas probes are generally higher in the fall and winter, and VOC detections in shallow soil-gas probes show more detections during winter, spring, and early summer.

Monitoring in wellheads and soil-gas probes around the 216-Z-12 Crib from 1992 to 1994 detected significant quantities of VOCs. The highest wellhead reading was 1,671 ppmv. Previous reports indicated that small quantities of VOCs had been disposed of to the crib. The source and distribution of these VOCs should be investigated further.

An array of multi-level soil-gas points was emplaced in mid-1993 and monitored until the end of 1993. Significant quantities of VOCs were detected in all points at depths ranging from 1.5 m to 33.2 m (5 to 109 ft) below surface. The highest level detected was 1,251 ppmv. This array is located between the 216-Z-1A Tile field and the 216-Z-12 Crib and infers that a broad plume exists between these two waste disposal sites.

Additional farfield wellhead monitoring farther from the carbon tetrachloride disposal sites in single point and multiple point arrays detected VOCs. As time allows, these anomalies should be investigated to determine the source of the VOCs.

ACKNOWLEDGEMENT

The author would like to thank Bob Schmitt for his efforts in collecting of the field data from the second half of fiscal year 1993 through December 1993. Bob also performed initial data workup and prepared most of the data graphs presented in this report. The work of Enserch Environmental in collating the field data into a workable database is also appreciated.

Carbon Tetrachloride Soil-Gas Baseline Monitoring

1.0 INTRODUCTION

1.1 PURPOSE

This report contains observations of the patterns and trends associated with data obtained during soil-gas monitoring at the 200 West Area Carbon Tetrachloride Expedited Response Action (ERA). Monitoring performed since late 1991 includes monitoring soil-gas probes and wellheads for volatile organic compounds (VOCs). This report reflects monitoring data collected from December 1991 through December 1993.

1.2 BACKGROUND

Carbon tetrachloride (CCl_4) was used in mixtures with other organics to recover plutonium from aqueous streams at the Plutonium Finishing Plant in the 200 West Area. Both the aqueous and organic phases of the waste stream were discharged to liquid waste disposal sites of various dimensions and construction. The commonality in design is generally a-pipe emptying into a gravel layer or emptying directly to the soil column. This allows for rapid infiltration of the waste stream into the soil column.

Organic liquids discharged to the cribs consisted of CCl₄ in mixtures with tributyl phosphate, dibutyl butyl phosphonate, or lard oil. Additional contaminants discharged to the cribs include metals, salts, and radionuclides.

It is estimated that a total of 363,000 to 580,000 L (96,000 to 150,000 gal) of CCl_4 -was discharged to the soil column between 1955 and 1973 (DOE/RL 1991) at three separate CCl_4 disposal areas. These disposal areas are the 216-Z-9 Trench, the 216-Z-1A Tile Field, and the 216-Z-18 Crib. The total amount of CCl_4 disposed to the soil represents less than 1/10 of the total liquid (mostly aqueous) disposed to the sites. Discharge of CCl_4 to the soil column was discontinued in 1973.

1.2.1 ERA Background

The 200 West Area Carbon Tetrachloride ERA is being conducted by the U.S. Department of Energy (DOE) at the direction of the U.S. Environmental Protection Agency (EPA) and the Washington State Department of Ecology (Ecology) as a provision included in the Comprehensive Environmental Response, Compensation and Liability Act of 1980 (CERCLA). The ERA was initiated based on concerns that the CCl₄ residing in the soils underlying the 200 West Area is continuing to serve as a source of groundwater contamination (DOE/RL 1992).

Based on the results of initial site investigations and an engineering evaluation and cost assessment, the preferred alternative chosen for removing carbon tetrachloride from the unsaturated zone was soil vapor extraction (DOE/RL 1991). In January 1992, the EPA and Ecology issued an action memorandum directing the initiation of soil vapor extraction. Vapor extraction is accomplished by applying a vacuum to selected wells located within the CCl₄ plume. CCl₄ vapors that are drawn off by the vacuum are adsorbed on granular activated carbon (GAC) contained in canisters. The loaded GAC canisters are transported offsite for regeneration.

2.0 SOIL-GAS BASELINE MONITORING

2,1 PURPOSE

The objectives of soil-gas baseline monitoring were originally defined in the vapor extraction system operation document (Green 1992). These objectives were:

- Measure existing concentrations of CCl₄ in the subsurface before initiating vacuum extraction, to provide a baseline.
- Investigate how the existing concentrations of CCl₄ vary with time.
- Evaluate the impact of vapor extraction on the distribution and concentrations of CCl₄ in the subsurface.
- Provide data to maintain a safe working environment.

As the ERA evolved, baseline monitoring objectives also matured. By fiscal year (FY) 1993, baseline monitoring included an expanded number of data points and farfield monitoring of unsampled wells and additional soil-gas points. FY 1993 objectives outlined in the Wellfield Enhancement Workplan (Rohay and Cameron 1993) were:

- Assist in characterization of the magnitude of the VOC plumes.
- Provide a baseline against which to evaluate the impact of the vapor extraction system on the plumes.
- Identify unknown VOC plumes.
- Provide a baseline to analyze VOC plume migration.

2.2 SCOPE

There are three types of monitoring discussed in this report: routine baseline monitoring, nonroutine farfield monitoring, and sealed well testing. Routine baseline monitoring was the emphasis of field work and is the emphasis of this report.

2.2.1 ROUTINE BASELINE MONITORING

Routine baseline monitoring began with 59 locations in the 200 West Area. In time, additional wells and soil-gas points were added and occasionally removed from the monitoring network. By the end of FY 1993 the baseline monitoring network encompassed 90 locations plus an array of multi-level soil-gas points (Figures 2-1, 2-2, and 2-3). These included 69 wellhead locations, 18 shallow soil-gas probes, 3 deep soil-gas probes, and 33 points at the multi-level soil-gas array (Table 2-1). Discrete samples were collected twice a week. Sampling was normally performed in a specific sequence generally between 9 a.m. and noon.

Sample LocationsNumber of LocationsDepthWellheads69Various (23-110 m)Shallow Soil-Gas Probes181.2 mDeep Soil-Gas Probes312, 20, and 30 mMulti-level Soil-gas Points331.5-33.2 m

Table 2-1. Routine Baseline Monitoring Locations

The 69 wells routinely monitored were installed over a long period of time (1954-1993) using various drilling and completion methods. Thirty-nine of these wells are vadose wells with depths ranging from 23 to 48 m (76 to 150 ft) below surface. Thirty of the wells are groundwater wells, with depth to water ranging from 58 to 65 m (190 to 213 ft) below surface. Most groundwater wells have screens straddling the top of the water surface, although some have deeper open areas (up to 182 m [600 ft] below surface). The various screen lengths are in lithologies including sands, gravels, cobbles, boulders, and clays. Figure 2-4 depicts typical well construction. Additional well construction diagrams can be found in DOE/RL (1991) and Rohay et al. (1992 and 1993). Appendix B presents limited construction data including casing size and type, depth to water, depth to bottom, and additional pertinent data for the wells monitored.

The 18 shallow soil-gas probes were all installed during 1991 and 1992 to a uniform depth of 1.2 m (4 ft). Figure 2-5 depicts a typical shallow soil-gas probe installation.

Figure 2-1. Baseline Monitoring Locations Near the ERA Site




Figure 2-2. Farfield Baseline Monitoring Locations




Figure 2-3. Multi-level Soil-Gas Point Locations





Figure 2-4. Typical Well Construction Diagram

	WELL CONSTRUCTION AND	COMPLETION SUMMARY	\neg
	Sample Method: Hard tool (nom) Additives Used: Not documented WA State Lic Nr: Not documented Company Location: ND ate pmplete: 21Jan59	WELL TEMPORARY NUMBER: 299-W15-95 WELL NO: Hanford Coordinates: N/S N 39,930 E/W W 75,925 State Coordinates: N 445,037 E 2,219,298 Start Card #:Not documented T R S Elevation Ground surface (ft): Not documented	-
Depth to water: Not applical GENERALIZED Driller's STRATIGRAPHY Log	ole.	Elevation of reference point: [660,00- (top of casing) Height of reference point above[ND ground surface	<u>-ft</u> 1
0-5: SAND & DIRT 5-13: SAND-GRAVEL 13-18: Pea GRAVEL 18-30: SAND-GRAVEL		Type of surface seal: None documented	_1
30-35: SAND-GRAVEL & COBBLE 30-35: SAND-GRAVEL & COBBLE 38-43: SAND 43-80: SAND & SILT 80-91: Sandy SILT 91-100: SAND & SILT		I.D. of surface casing <u>[ND</u> (If present)	j
		I.D. of riser pipe: [<u>8-in</u> Type of riser pipe: Carbon steel	<u>1</u>
		Type of filler: Not documented Elevation/depth top of seal	<u>10m</u>]
		Type of seal: Not documented No perforations documented:	
		Depth bottom of casing Depth bottom of borehole: [100-fi	<u>t</u>]
Drawing By: <u>RKL/2W15-95.ASB</u> Reference: <u>HANFORD WELLS</u>	Date: <u>09Dec92</u>	·	

Figure 2-5. Typical Shallow and Deep Soil-Gas Probe Installations



Three deep soil-gas probes are emplaced near the 216-Z-9 Trench. The 20 m (69 ft) probe (CPT 15-6) was installed in September 1991. Probe CPT 15-84 was emplaced in August 1992 at a depth of 12 m (39 ft). Probe CPT PNL-5 was installed at a depth of 30 m (98 ft) in April 1993.

During mid-1993 a cone penetrometer was used to install soil-gas points west of the 216-Z-1A Tile Field (Richterich 1993) in support of tracer gas testing at the ERA site. Multi-level soil-gas points were emplaced at many of the locations. Thirty-three soil-gas points were emplaced at depths ranging from 1.5 to 33.2 m (5 to 109 ft) below surface. Figure 2-6 shows a typical installation of multi-level soil-gas points.

2.2.2 NONROUTINE FARFIELD MONITORING

Nonroutine farfield monitoring was the one-time measurement of VOCs in other wells in the 200 West Area. During FY 1993, nonroutine VOC monitoring was performed on 111 wells. These wells were both vadose zone and groundwater wells.

2.2.3 SEALED WELL TESTING

Sealed well testing used a simple field method to estimate the amount of air flowing into or out of wells under varying conditions. Sealed well testing was performed four times.


2.3 SAMPLING METHODS

Monitoring is performed at EPA analytical level I (field screening). The sampler approaches the sample location from an upwind direction while monitoring the breathing zone air with a photo-ionization detector (PID). If there are any readings in the breathing zone, the sampler uses a colorimetric tube for CCl₄ to test the breathing zone. If any CCl₄ is confirmed, the sampler exits the work area and contacts the site safety officer.

To begin the wellhead sampling routine, the sampler monitors around the edge of the well cap to obtain a background reading, then lifts the well cap and inserts the PID probe a few centimeters into the well. The sampler allows air to be drawn through the instrument for at least ten seconds to fully equilibrate the system. At multi-level sampling wells (a packer separates two screened intervals), each interval is individually sampled and then resealed.

At soil-gas probes, the sampler takes a background reading a few centimeters from the sample tube and then directly couples the PID to the tube. The sampler extracts at least two purge volumes from the tube before taking the sample. This is done to ensure the sample represents soil-gas, not residual air in the sample tube.

Figure 2-6. Typical Multi-Level Soil-Gas Probe Installation



At both wellheads and soil-gas probes the sampler draws air through the instrument while monitoring the real-time readings. This continues while the readings increase. Once the reading has peaked, the sampler records the maximum value on a data sheet and stores it in the instrument.

2.4 MONITORING INSTRUMENTS

CCl $_4$ has an ionization energy potential of 11.47 eV and must be monitored with an instrument that has a lamp output greater than 11.47 eV. Monitoring for this project was performed using a Thermo Environmental Instruments Model 580 PID equipped with an 11.8 eV lamp. The range for the instrument is 0.1 to 2,000 ppmv in a benzene-in-air matrix (Thermo Environmental Instruments Inc. 1991). Previous analysis (DOE/RL 1991 and Rohay 1992) with a gas chromatograph indicates that CCl $_4$ is the primary VOC present in the wellheads and soil-gas probes. The presence of CCl $_4$ is confirmed at selected sample stations using CCl $_4$ -specific colorimetric tubes manufactured by DRÄGERWERK AG LÜBECK. Based on these results it is assumed that the VOC measured with the PID is CCl $_4$.

Monitoring instruments are maintained and calibrated daily in accordance with Environmental Investigations Instruction (EII) 3.2 (WHC-CM-7-7). Isobutylene calibration standards are certified and traceable to a national or industry recognized standard.

During FY 1992 and part of FY 1993, the PID response factor was set at 1.0. During mid-FY 1993, at the request of the Westinghouse Hanford Company (WHC) safety organization, the PID response factor was changed to 5.0. This change made the PID more sensitive to VOCs at lower concentrations. Data collected with a response factor of 5.0 have been converted to reflect output as if the original response was 1.0.

If sample readings are not reproducible or sample readings vary for no apparent reason, the instrument is challenged with calibration gas. If the challenge is not within 10% of the original calibration the instrument is recalibrated. At the end of each day's sampling the instrument is challenged with a calibration standard.

2.5 SAMPLING DATA

Data acquired from baseline monitoring are entered on a data sheet and are logged internally within the instrument for later retrieval. Copies of the original field data sheet and instrument printout are maintained in accordance with EII 1.6 (WHC-CM-7-7).

The raw data for the FY 1992 monitoring were presented in a previous publication (Fancher 1993). Raw data for FY 1993 and 1994 monitoring can be found in a series of reports (Rohay 1994 a through g). Data in these reports include sample date, sample location name, sample location number, sample time, background reading, sample reading, reading minus background, the instrument response factor, and individual comments.

Appendix A presents a cumulative maximum, minimum, and average value (including non-detects) for each sample location as well as an average of the detections at each location and the number of samples (including non-detects) and the number of detections (positive points) at each station.

When the term "average" is used in this report it refers to the average of the positive points (detections) of a sample point. The "average" value represents the average concentration that is being vented when air is flowing out of the well. When there are no detections, air is usually flowing into the well; therefore, the average including the non-detects is not used in this report.

Several maps in this report (Figures 4-2, 4-3, and 4-5) contour the maximum VOCs detected in wellheads or soil-gas probes. It was decided to contour the maximum values because they most likely represent equilibrium values. It was believed the maximum value was the equilibrium because the concentrations range from zero to the maximum (equilibrium), depending on barometric pressure fluctuations (and the resultant air inflow [zero detections] or outflow [positive detections]).

3.0 ROUTINE BASELINE MONITORING DATA DISCUSSION

3.1 WELLHEAD SAMPLING DATA

The maximum wellhead detection of VOCs exceeded the field instrument's capacity of 10,000 ppmv at two wellheads: 299-W15-82 and 299-W15-95 (at the 216-Z-9 Trench). Eight additional wells had maximum VOC concentrations exceeding 1,000 ppmv, five of them located at the 216-Z-9 Trench.

The lowest average value of VOCs detected in an ERA site wellhead was 1 ppm at 299-W18-88, and the highest average value was 651 ppm at 299-W15-82. Results of wellhead sampling indicate that concentrations of VOCs vary widely over time and space (Fancher 1992). During the course of sampling, readings ranged from non-detections to several hundred parts per million, and occasionally detections were over 10,000 ppmv.

Appendix B presents limited construction data including casing size and type, depth to water, and depth to bottom. Appendix B also contains the calculated total subsurface open area for the wells monitored. For purposes of this report, open area is defined as the total square inches of well casing open to the subsurface soil (vadose zone).

It is known that wellhead VOC detections (and airflow into and out of wells) are affected by barometric pressure. During periods of low pressure, VOC concentrations are higher. Rohay and Cameron (1992a and 1992b) have previously discussed these effects. Additional work is ongoing. Further discussions are beyond the scope of this report.

3.2 SHALLOW SOIL-GAS PROBE DATA

Levels detected in shallow soil-gas probes are generally lower than levels detected in deep soil-gas probes or wellheads. The highest shallow probe value detected was 132 ppmv at SG 94-02 (northwest of 216-Z-9), while the highest wellhead value detected was over 10,000 ppmv. The distances between a given CCl_4 disposal site and probe locations range from 0 to 58 m (190 ft). Of the 18 stations routinely monitored, the lowest average of the detected values was 3.9 ppmv, and the highest average of the detected values was 27.9 ppmv.

3.3 DEEP SOIL-GAS PROBE DATA

Three deep soil-gas probes are emplaced at the 216-Z-9 Trench. The 20 m (65 ft) deep probe (CPT 15-6) regularly yields high VOC measurements. Results from this probe range from 0 ppmv to over 10,000 ppmv. The average value of VOC levels detected was 1,613.1 ppmv.

The shallower probe, CPT 15-84, was emplaced in August 1992 at 12 m (39 ft). The data set has lower values (0 to 259 ppmv), but often has elevated values on days CPT 15-6 also has elevated readings. The average value of the detections was 28.6 ppmv.

The deepest of the three deep probes, CPT PNL-5, at 30 m (98 ft) deep, was monitored during emplacement and provided detection of CCl₄ ranging in the hundreds of ppmv. After emplacement sampling, the outer steel rods were removed, and the sampling tube was grouted in place. Sampling attempted after emplacement rod removal has not proven successful. Samples were collected on 58 occasions, but VOCs were detected on only 9 occasions. VOC levels detected ranged from 0 to 12.4 ppmv, with an average value of 4.7 ppmv.

3.4 MULTI-LEVEL SOIL-GAS POINTS

Seventy meters (230 ft) west of the 216-Z-1A Tile Field an array of 33 multi-level soil-gas points was emplaced to support tracer gas testing. Many of these points were monitored during the last half of 1993. The highest VOC level detected at the multi-level soil-gas array was 1,251 ppmv at point CPT-4C at 22.8 m (75 ft) deep. The lowest average value of detections at the array was 7 ppmv at CPT-4J at 7.6 m (25 ft), and the highest average of detections was 94 ppmv at CPT-4C at 22.8 m (75 ft).

3.5 216-Z-12 CRIB

Crib 216-Z-12 is located northwest of Crib 216-Z-18 and west of the 216-Z-1A Tile Field. Initially only a few wells were monitored on the south and east of the crib. Concentrations of VOCs in wells and soil-gas probes were higher than expected considering the small quantity of VOCs believed to have been sent to the crib (DOE/RL 1991). In FY 1993 additional wells were monitored around the crib.

The 216-Z-12 Crib received laboratory wastes containing primarily nitrates and a small quantity of CCl_4 . The crib is radiologically controlled as an underground radioactive materials area. The highest wellhead reading was 1,671.5 ppmv at 299-WI8-153 (east of 216-Z-12), higher than other wellheads at 216-Z-1A or 216-Z-18.

---The highest seil-gas probe reading-was 97 ppmv at station SG N-9 (east of 216-Z-12), higher than detections at 216-Z-1A or 216-Z-18.

Possible explanations for these high detections include preferred movement of VOCs from the 216-Z-1A Tile Field because of underlying geologic features, or VOCs sent to the 216-Z-12 Crib but not recorded.

3.6 FARFIELD MONITORING

During FY 1993, additional wells north and south of the ERA were added to the routine biweekly monitoring. All but one of these wells with detectable VOCs were screened below the caliche horizon in the groundwater. The origin of these VOC detections is likely VOCs in the groundwater. The ultimate source of these contaminants is beyond the scope of this report. Wells were located near:

- T Tank Farm
- TX Tank Farm
- TY Tank Farm
- 216-Z-7 Crib
- 216-Z-12 Crib
- 216-T-19 Crib
- 216-Z-20 Crib

VOC detections indicate the possibility of additional areas of deep unsaturated zone contamination. These areas are known to be contaminated with CCl_4 in the groundwater. Table 3-1 lists farfield monitoring wells where detected VOC concentrations were greater than 1 ppmv. The highest farfield detection was 49.8 ppmv, recorded at well 299-W15-4, located west of the 216-T-19 Crib. This crib is known to have had CCl_4 discharged to it (Rohay et al. 1993b). Figure 3-1 shows farfield wells monitored and indicates whether VOCs were detected, and the maximum concentrations detected.

Figure 3-1. Maximum VOC Concentrations Detected at Routine Farfield Monitoring Wells




Table 3-1. Routine Farfield VOC Detections

Well Number	Max ppmv	Number of Detects	Number of Samples	Depth (ft) Top of Open Interval	Area
299-W10-9	3.9	3	84	202	North of T Tank Farms
299-W11-1	2.3	3	84	220	West of T Plant
299-W14-12	3.8	2	84	198	East of TX Tank Farm
299-W15-4	49.8	3	80	170	West of T-19 Crib
299-W15-12	4.3	<u>3</u>	84	195	West of TY Tank Farm
299-W15-22	9.6	4	85	198	Southwest of TX Tank Farm
299-W15-76	2.3	3	83	103	216-Z-7 Crib; only well open above caliche

4.0 COMPARISON OF SAMPLING DATA SETS

4.1 PATTERNS OF WELLHEAD CONCENTRATIONS

Wellhead concentrations are highest at the 216-Z-9 Trench by nearly an order of magnitude above concentrations at other areas of the ERA. Commonly venting wells have average detection values in the 26 to 651 ppmv range. The highest wellhead readings exceeded the PID capacity of 10,000 ppmv at 299-W15-95 and 299-W15-82. Figure 4-1 is a plot of maximum VOC concentrations over the entire 25 months of baseline monitoring at Well 299-W15-82. A seasonal trend of generally higher VOC detections in the fall and winter months is evident.

Concentrations of VOCs were highest at the 216-Z-9 Trench, where levels exceeded 10,000 ppmv at two wells, and at one deep soil-gas probe. Records provide a wide ranging estimate (83,000 to 300,000 L [95,895 to 153,220 gal]) of carbon tetrachloride disposed to the 216-Z-9 Trench. If the smaller quantity is correct, the 216-Z-9 Trench received the least amount of carbon tetrachloride of any waste area in the ERA. If the larger quantity is correct, the 216-Z-9 Trench received the most carbon tetrachloride of any waste area in the ERA. Another possible factor contributing to VOC concentrations is the trench size; it is the smallest of any waste area in the ERA.

299-W15-82 VOC CONCENTRATION IN PPM

Figure 4-1. Maximum VOC Concentrations over Time at Well 299-W15-82

Concentrations of VOCs are highest in wells with subsurface openings (perforations or screen) above a local semi-confining geologic feature. The Plio-Pleistocene Unit (34 to 44 m [111 to 144 ft] below surface) contains a horizon of caliche stringers, concretions, and carbonate rich alluvial silts, sands, and gravels (Singleton and Lindsey 1994). The semi-confining caliche layer has a very low hydraulic conductivity. Figures 4-2 and 4-3 present contours of the maximum VOC concentrations measured in wells above and below the caliche horizon. Figure 4-4 graphically presents maximum VOC concentrations of wells routinely monitored.

Distance between a well and the waste disposal area also influences levels of VOCs detected in wellheads. Higher levels are generally detected in wells located very near waste sites than in wells farther away. In wells with subsurface openings below the caliche layer, higher levels of VOCs were detected in the wells perforated or screened just above the groundwater than in those with openings significantly above the groundwater.

Examination of wellhead measurements collected above and below the caliche horizon provides additional insight into the distribution of VOC levels detected at wellheads. Figure 4-5 compares the maximum VOC concentrations over time above and below the caliche horizon at well 299-W15-216. In the area of the 216-Z-9 Trench, the highest above-the-caliche measurements (10,000 ppmv) were collected to the north and east. Lesser though still significant levels were detected to the west. To the south, VOC levels diminished. Below the caliche the maximum detections are found to the northeast.

In the areas of the 216-Z-1A Tile Field and the 216-Z-12 Crib, the maximum levels detected above the caliche fall within the 1,000 ppmv contour in an east-west band stretching from the 216-Z-1A Tile Field to the 216-Z-12 Crib. The VOC levels below the caliche in this area follow a similar pattern but indicate a much smaller area of maximum concentrations. VOCs at the 216-Z-18 Crib occur at significantly lower concentrations and occur in the eastern half of the crib (the western most trench in the 216-Z-18 Crib was never used).

No correlation appears to exist between a well's open area (square inches of subsurface area open to the vadose zone) and maximum parts per million. Some wells with large open areas have high average VOC detections, and others have low average detections. This seems reasonable, considering that some deep soil-gas probes (with an extremely small open area) have VOC concentrations higher than some wellhead concentrations.

Appendix B provides data on individual wells, including casing diameter, well depth, perforation and well screen intervals, and total area of the subsurface (perforation or screen) open to the subsurface. Appendix C explains the method used to calculate the well open areas.

Figure 4-2. Contours of Maximum VOC Concentrations in Wells Screened Above Caliche







Figure 4-3. Contours of Maximum VOC Concentrations in Wells Screened Below Caliche



BASELINE MONITORING



299-W15-216 UPPER AND LOWER INTERVALS



Levels of VOCs detected in wellheads are affected by barometric pressure. Rohay and Cameron (1992a and 1992b) discuss this relationship. During periods of low barometric pressure, VOC-concentrations are higher. This fact has been confirmed on many occasions during field work conducted for this report. Additional related investigative work is underway but is beyond the scope of this report.

4.2 PATTERNS OF SHALLOW SOIL-GAS CONCENTRATIONS

Shallow soil-gas probe VOC concentrations are highest at the 216-Z-9 Trench. At the 216-Z-9 Trench the highest concentration, 132 ppmv, was detected 50 m (164 ft) to the northwest, but relatively high levels were also detected to the south and northwast. In the 216-Z-1A area, the highest shallow soil-gas concentration was 97.4 ppmv, detected 5 m (16 ft) east of the 216-Z-12 Crib. The maximum VOC concentrations detected in shallow soil-gas probes are contoured in Figure 4-6. VOC concentrations at soil-gas probe SG N-9 (located east of the 216-Z-12 Crib) are depicted in Figure 4-7.

Figure 4-8 depicts the shallow soil-gas probe detections and non-detections for each sampling day over the 25-month period. Detections appeared fairly consistently during the first year of monitoring. An apparent seasonality is shown by a high percentage of detections between February and July 1992, and many non-detects during September and October. The pattern appears to continue in 1993, but in a muted form; the muting is believed to be caused by the addition of soil-gas points to the routine monitoring network in January 1993. Detections at these added probes (at the 216-Z-9 Trench) occurred more frequently than at probes in other areas.

4.3 PATTERNS OF DEEP SOIL-GAS CONCENTRATIONS

All three deep soil-gas probes are located at the 216-Z-9 Trench. Due to the limited number of data points, the patterns observed were increasing VOC detections during periods of falling or low barometric pressure, and a seasonal trend of generally higher VOC detections in the fall and winter months. Figure 4-9 depicts probe CPT-15-6 maximum concentrations over the entire 25 months of baseline monitoring.

4.4 PATTERNS OF MULTI-LEVEL SOIL-GAS POINT CONCENTRATIONS

Concentrations of VOCs detected at the multi-level soil-gas array vary widely over time. Previously, Rohay and Cameron (1992a) discussed changing soil-gas concentrations. Figure 4-10 depicts the concentrations detected from five different intervals at location CPT 4F. At most sampling events VOCs were detected in at least one interval in the array location. The highest number of maximum detections were recorded from the 23 m (75 ft) deep point. The 23 m (75 ft) deep point also has the most number of maximum detections. Patterns emerging include a close relationship between the 23 and 32 m (75 and 109 ft) deep points.

The highest detection from this location was recorded at the 8 m (25 ft) deep probe. Every depth location at CPT 4F at one time or another recorded a day's maximum VOC detection.

Figure 4-6. Contours of Maximum VOC Concentrations in Shallow Soil-Gas Probes




Figure 4-7. Maximum VOC Concentrations over Time at Shallow Soil-Gas Probe SG N-9




Figure 4-8. Shallow Soil-Gas Probe Detections






Figure 4-9. Maximum VOC Concentrations over Time at Deep Soil-Gas Probe CPT-15-6 VOC CONCENTRATION IN PPM




4.5 COMPARING SOIL-GAS, AND WELLHEAD CONCENTRATIONS

Concentrations of VOCs detected in shallow soil-gas probes in most cases are lower than levels detected in deep soil-gas probes or wellheads. The highest shallow probe value detected was 132 ppmv while the highest wellhead value detected was over 10,000 ppmv. One of the 3 deep soil-gas probes recorded high (>10,000 ppmv) VOC concentrations. Figure 4-11 compares VOC concentrations from a wellhead and nearby deep soil-gas probe. In nearly all cases the deep soil-gas probe had higher concentrations.

Figure 4-12 shows VOC concentrations from the same wellhead and deep soil-gas probe compared with VOC concentrations in a nearby shallow soil-gas probe. Again the deep soil-gas probe had highest concentrations, but the shallow soil-gas probe occasionally had higher VOC concentrations than the wellhead. Because of various emplacement depths and differing emplacement locations, additional comparisons between soil-gas and wellhead VOC concentrations are difficult.





5.0 NONROUTINE FARFIELD MONITORING

During FY 1993, as time allowed, other wells in the 200 West Area were also monitored for VOCs. This additional monitoring was performed when the two following criteria were met: barometric pressure was at or below 29.0 in. of Hg., and sampling personnel were available. Routine sampling occupied two days of the five-day work week, so samplers were not always available on an on-call basis. A total of 111 wells were monitored on a one-time basis.

Health—and—safety monitoring data—were—also—collected farfield by well maintenance crews. Much of these data provided additional information about wells that were routinely used to take water samples, perform geophysical logging, and take water level measurements. New information about VOC emissions from a few previously unmonitored wells was provided.

Table 5-1 lists single point detections from farfield monitoring and health and safety monitoring. Appendix D presents a table listing all wells sampled during nonroutine farfield monitoring. Figure 5-1 shows nonroutine farfield wells monitored and indicates whether VOCs were detected. VOCs were detected in areas outside the original baseline monitoring area including:

- Southeast of U Tank Farm
- East of Crib 216-Z-7.

N46000 N45000 N44000 9 241-T W N43000 241-TY TANK FARM N42000 TANK FARM N41000 284-W Powerhouse Pond 19th Street N40000 N39000 N38000 Legend N37000 O No VOCs Detected 1000 Feet VOCs Detected, Welt Screened Below Coliche

Figure 5-1. Nonroutine Farfield Monitoring Wells and VOC Detections

300 Meters

GEOSCI\040894-A

■ VOCs Detected, Well Screened Above Caliche

Well Number	Maximum ppmv	Depth (ft) Top of Open Interval	Area
299-W15-1	11	190	E of 216-Z-7 Crib
299-W19-27	17	208	SE of U Tank Farm
299-W19-91	13	110	SE of U Tank Farm; only well open above caliche

Table 5-1. Nonroutine Farfield VOC Detections

6.0 SEALED WELL TESTS

On four occasions, wells in the monitoring network were tested to estimate the relative amount of air inflow or outflow. After the well cap was removed, a small plastic bag was placed over the wellhead. This bag was tightly sealed by constricting the bag to the outer casing-surface. A subjective measurement of airflow (high/medium/low) into or out of the well was then noted, based on how quickly the bag was either filled with or evacuated of air. Wells with air flowing into the well were noted as negative, while wells with air flowing out were recorded as positive.

Figures 6-1, 6-2, 6-3, and 6-4 depict the sealed well tests. The most interesting test was conducted April 13 (Figure 6-1). On this date, a change occurred in subsurface pressure; the upper vadose zone above the caliche layer had lower pressure than the atmospheric pressure, so air was flowing into most of these wells. Pressure in wells below the caliche layer, on the other hand, was mainly positive, causing vapors to exit the wellhead.

During testing on August 3 and December 3, 1993, air in all wells was observed to be either venting from wells or neutral (neither venting from nor moving into wells). During the test on December 28, 1993, air in all wells was either moving into wells or neutral.

Figure 6-1. Sealed Well Test April 13, 1993


The Press Vice of the
Press; 23.17
29.18
NI NI NI NI NI NI NI NI
Y10-10 Y
V10-04 V10-67 (1) - 67<
VID-217 VID-25 VID-26 VID-26 VID-27 VID-26
Vig-217 Vig-26 Vig-26 Vig-26 Vig-27 Vig-27 Vig-27 Vig-27 Vig-27 Vig-27 Vig-27 Vig-26 Vig-27
Yib-eb Xib-eb X
WIS-217 WIS-240 WIS-240 WIS-260 WIS-240 WIS-260 WIS-240 WIS-260 WIS-260 WIS-260 WIS-260 WIS-260 WIS-261 WIS-261 WIS-261 WIS-261 WIS-261 WIS-261 WIS-261 WIS-261 WIS-262 WIS-261 WIS-262 WIS-262 WIS-262 WIS-262 WIS-262 WIS-262
VIG-157 VIG-247U VIG-167 VIG-247U VIG-240 VIG-247U VIG-240 VIG-50 VIG-50 VIG-60 VIG-60 VIG-60 VIG-60 VIG-61 VIG-60 VIG-10 VIG-10 VIG-10 VIG-10 VIG-10 VIG-10 VIG-10 VIG-12 VIG-10 VIG-12 VIG-12 VIG-13 VIG-12 VIG-14 VIG-12 VIG-15 VIG-12 VIG-16 VIG-12 VIG-16 VIG-12 VIG-16 VIG-12 VIG-16 VIG-12 VIG-16 VIG-16 VIG-16 VIG-16 VIG-16 VIG-16 VIG-16 VIG-16
VID-217 VID-247U VID-247U VID-247U VID-247U VID-248U VID-247U VID-247U VID-248U VID-247U VID-248U
VIO-157 VIO-270 VIO-270 VIO-270 VIO-260 VIO-260 VIO-260 VIO-260 VIO-260 VIO-260 VIO-260 VIO-260 VIO-270 VIO-260 VIO-
vi6-247U vi8-247U vi6-246 vi8-60 vi6-9 vi6-9 vi6-9 vi6-9 vi6-8 vi6-10 vi6-80 vi6-247L vi6-10 vi6-10 vi6-10 vi6-20 vi6-20 vi6-20
W18-247U W18-247U W18-26U W18-26U W18-60 W18-60 W18-60 W18-60 W18-60 W18-60 W18-67 W18-10 W18-
Vi6-246 Vi6-90 Vi6-90 Vi6-90 Vi6-90 Vi6-90 Vi6-90 Vi6-90 Vi6-90 Vi6-90 Vi6-10
W18-50 W18-20 W18-10 W
W16-240 W16-90 W16-90 W16-90 W16-90 W16-90 W16-80 W16-80 W16-80 W16-24 W16-10
Vid-240 Vid-90 Vid-90 Vid-90 Vid-90 Vid-90 Vid-90 Vid-80 Vid-80 Vid-80 Vid-10
V16-90 V16-10 V
VIG-DS V
VIG-05 VIG-05 VIG-05 VIG-05 VIG-05 VIG-05 VIG-05 VIG-05 VIG-06 V
V15-80 V18-67 V18-67 V18-67 V18-67 V18-67 V18-18 V
Vie.ep V
V10-02 V10-03 Calcale La V10-04 Calcale La V10-05 V10-06 V10-06 V10-06 V10-06 V10-10 V1
1.
W16-2471. W16-16 W16-16 W16-16 W16-16 W16-17 W16-2 W16-2 W16-2
11.
W10-5 W10-10 W10-17 W10-17 W10-17 W10-17
61. W16-5 W18-16 W18-16 W18-17 W18-17 W18-17 W18-24
Mile-16 Wile-16 Wile-16 Wile-16 Wile-17 Wile-17 Wile-2
V10-19 V10-19 V10-17 V10-17 V10-17 V10-17
W10-10 W10-10 W10-1 W10-1 W10-1 W10-17 W10-2
Y10-6
¥16-6
¥16-6
¥16-6
¥16-6
¥16-6 ¥16-1
¥16-6
¥10-6
¥16-1
¥16-1
W10-1
0-01-

Air flow is rated in increments of 5 corresponding to HIGH, MED, and LOW in either a positive (out) or negative (in) direction.

Method of detection used was a plastic bag sealed over the well head opening.


•			i gu	re				Se	a	led	d V			Г	7	Ai	l lg	us	t	3,	1	99)3						7 8	,
		V16-62		W18-96	W15-P8		V15-217						W18-9	Wi8-65	T allows		٩						- 12			#16-2		54	32	
·	9900 -00		16-91 A			¥118-63								Ä			W15-5		#16-60				¥18-12					V18-24	01	ements of 5 corresponding to 1100 and 1
s Test			10-10				W18-157	W16-153		W. 8-85			¥15-66	V10-62					W18-11		¥18-18	W15-8					-10-16	W15-8	.	
Sealed Wells Test																													Air Flow	
		- - -				-			-					iyer															· \$7	Company of F
	V3/93	29.11												Caliche La														- -	- 10	Air flow is rated in incr
an a wala waka ku wa ku wa	Performed & Time:	- 1																										 	9	
· · · · · · · · · · · · · · · · · · ·	8.55 8.85 8.10 1	4 4 4 8 8 8	8 8	1 2 2	8 8	-110.00	8.0	80.00	89.12.18	14 1 18 8 1 1	28 8 8 8 8 8	91 8 8	8.5 2.5 3.5 3.5 3.5 3.5 3.5 3.5 3.5 3.5 3.5 3) (1) 8 8 1	19(1 8) 8 1	173.80	8.8.8	90.08	180.00	-165.00	9,56	-190.00	00.00	-105.00	-200.00	200.00	209.00	 - 8	ŧ	

38



Sealed Wells Test

Sealed Wells Test



Air flow is rated in increments of 5 corresponding to HIGH, MED, and LOW in either a positive (out) or negative (in) direction.

Method of detection used was a plastic bag sealed over the well head opening.

7.0 CONCLUSIONS

Concentrations of VOCs were highest at the 216-Z-9 Trench, where measurements exceeding 10,000 ppmv were taken on several occasions. VOCs were also detected during routine monitoring at the 216-Z-1A Tile Field and the 216-Z-1B Crib, where maximum concentrations were 1,532 and 442 ppmv, respectively.

During monitoring near the 216-Z-12 Crib, significant quantities of VOCs were detected in wellheads and soil-gas probes. The highest wellhead reading was 1,672 ppmv, and the highest soil-gas reading was 132 ppmv. Both of these measurements were taken east of the 216-Z-12 Crib. Previous reports (DOE 1991) indicate small quantities of VOCs_were_disposed_of_to the_crib._ The source_of_these VOCs should be investigated.

Concentrations of VOCs are higher in wells with subsurface openings (perforations or screen) above the semi-confining caliche horizon. Distance between a well and the waste disposal area also affects VOC levels detected in wellheads. Wells located very near waste sites generally have higher levels than wells farther away. Wells with subsurface openings perforated or screened in or just above the groundwater have higher VOC levels than those with openings also below the caliche but significantly above the groundwater.

Two seasonal trends are apparent as indicated by graphs of wellhead and soil-gas probe concentrations. VOC concentrations in wellheads and deep soil-gas probes are generally higher in the fall and winter months. VOC detections from shallow soil-gas probes show an apparent seasonality of more detections during winter, spring, and early summer.

An array of multi-level soil-gas points was emplaced between the 216-Z-1A Tile Field and the 216-Z-12-Crib in mid-1993. These points were monitored until the end of 1993. Significant quantities of VOCs were detected in all points. The highest level detected was 1,251 ppmv. These results indicate that a broad plume likely exists between these two waste disposal sites.

Additional wellhead monitoring farther from the carbon tetrachloride disposal sites detected VOCs in single point and multiple point detections. Many of these detections occurred at other waste disposal sites. These anomalies should be investigated to determine the source of the VOCs.

This report is being provided to WHC safety, well maintenance, subsurface geophysics, and groundwater sampling groups. These data may be useful in planning work at wells where VOCs have been detected.

A solid baseline of VOC concentrations in wells and soil-gas at the ERA site has been established. As site remediation continues, comparisons to this baseline can be one means of measuring the success of vapor extraction and other site remediation methods.

8.0 REFERENCES

- DOE/RL, 1991, Expedited Response Action Proposal (EE/CA & EA) for the 200 West

 Area Carbon Tetrachloride Plume, DOE/RL-91-32, Draft B, U.S. Department of Energy, Richland, Washington.
- DOE/RL, 1992, 200 West Area Groundwater Aggregate Area Management Study Report, DOE/RL-92-16, Decisional Draft, U.S. Department of Energy, Richland, Washington.
- Fancher, J. D., 1992, Field Observations of Variability of Soil Gas Measurements, WHC-SA-1763-FP, Westinghouse Hanford Company, Richland, Washington.
- Fancher, J. D., 1993, 200 West Carbon Tetrachloride Expedited Response Action Baseline Monitoring Data Package, WHC-SD-EN-DP-063, Rev. O, Westinghouse Hanford Company, Richland, Washington.
- Green, J. W., 1992, Design, Operation, and Monitoring of the Vapor Extraction System at the 216-Z-IA Tile Field, WHC-SD-EN-TI-010, Rev. 0, Westinghouse Hanford Company, Richland, Washington.
- Last, G. V. and V. J. Rohay, 1993, Refined Conceptual Model for the Volatile Organic Compounds-Arid Integrated Demonstration and 200 West Area Carbon Tetrachloride Expedited Response Action, PNL-8597, Pacific Northwest Laboratory, Richland, Washington.
- Richterich, L. R., 1993, Fiscal Year 1993 Heavy Weight Cone Penetrometer Activities at the Hanford Site, WHC-SD-EN-TRP-006, Rev. O, Westinghouse Hanford Company, Richland, Washington.
- Rohay, V. J., 1994a, Carbon Tetrachloride Expedited Response Action Wellfield Data Report for October and November 1992, WHC-SD-EN-DP-072, Rev. 0, Westinghouse Hanford Company, Richland, Washington.
- Rohay, V. J., 1994b, Carbon Tetrachloride Expedited Response Action Wellfield
 Data Report for December 1992 and January 1993, WHC-SD-EN-DP-073, Rev. 0,
 Westinghouse Hanford Company, Richland, Washington.
- Rohay, V. J., 1994c, Carbon Tetrachloride Expedited Response Action Wellfield Data Report for February and March 1993, WHC-SD-EN-DP-074, Rev. 0, Westinghouse Hanford Company, Richland, Washington.
- Rohay, V. J., 1994d, Carbon Tetrachloride Expedited Response Action Wellfield
 Data Report for April and May 1993, WHC-SD-EN-DP-075, Rev. 0, Westinghouse
 Hanford Company, Richland, Washington.
- Rohay, V. J., 1994e, Carbon Tetrachloride Expedited Response Action Wellfield
 ——Data Report for June and July 1993, WHC-SD-EN-DP-076, Rev. 0, Westinghouse
 Hanford Company, Richland, Washington.

- Rohay, V. J., 1994f, Carbon Tetrachloride Expedited Response Action Wellfield
 --- Data Report for August and September 1993, WHC-SD-EN-DP-077, Rev. 0,
 Westinghouse Hanford Company, Richland, Washington.
- Rohay, V. J., 1994g, Carbon Tetrachloride Expedited Response Action Wellfield
 Data Report for October, November and December 1993, WHC-SD-EN-DP-078, Rev. 0,
 Westinghouse Hanford Company, Richland, Washington.
- Rohay, V. J. and R. J. Cameron, 1992a, "Field Observations of Volatile Organic Vapor Phase Distribution and Movement at the Hanford Site, Washington," *Transactions*, American Geophysical Union, Vol. 73, no. 14, Spring meeting.
- Rohay, V. J. and R. J. Cameron, 1992b, "Field Measurements of Natural Soil-Gas Venting Cycles in Boreholes at the Hanford Site, Washington," *Transactions*, American Geophysical Union, Vol. 73, no. 43, Fall meeting.
- Rohay, V. J. and R. J. Cameron, 1993, FY93 Wellfield Enhancement Workplan for the Carbon Tetrachloride ERA, WHC-SD-EN-AP-114, Rev. O, Westinghouse Hanford Company, Richland, Washington.
- Rohay, V. J., G. V. Last, D. C. Lanigan, and L. A. Doremus, 1993, FY93 Site Characterization Status Report and Data Package for the Carbon Tetrachloride Site, WHC-SD-EN-TI-202, Rev. O, prepared by V. J. Rohay, K. J. Swett, and V. M. Johnson, Westinghouse Hanford Company, and G. V. Last, D. C. Lanigan, and L. A. Doremus, Pacific Northwest Laboratory, for Westinghouse Hanford Company, Richland, Washington.
- Rohay, V. J., K. J. Swett, G. V. Last, D. C. Lanigan, and L. A. Doremus, 1992, FY92 Site Characterization Workplan for the Volatile Organic Compounds Arid Integrated Demonstration and the 200 West Area Carbon Tetrachloride Expedited Response Action, WHC-SD-EN-AP-109, Rev. 2, Westinghouse Hanford Company, Richland, Washington.
- Singleton, K. M. and K. A. Lindsey, 1994, Groundwater Impact Assessment Report for the 216-U-14 Ditch, WHC-EP-0698, Rev. O, Westinghouse Hanford Company, Richland, Washington.
- Thermo Environmental Instruments Inc., 1991, Model 580 Field Guide, Franklin, Massachusetts.
- WHC-CM-7-7, Environmental Investigations and Site Characterization Manual, Westinghouse Hanford Company, Richland, Washington.

APPENDIX A

BASELINE MONITORING STATISTICS - DECEMBER 1991 THROUGH DECEMBER 1993

		• *		'		
SAMPLE POINT	MAXIMUM	MINIMUM	AVERAGE	AVERAGE	# SAMPLES	# SAMPLES
	(all points)	(all points)	(all points)	(all positive points)	(all points)	(all positive points)
CPT 15-6	10400.0	0.0	1534.41	1613.10	205	195
CPT 15-84	259.0	0.0	17.72	28.65	131	81
CPT PNL-5	12.4	0.0	0.74	4.75	58	9
CPT-4B 5'	1093.4	0.0	39.23	78.45	38	19
CPT-4B 25'	137.8	0.0	17.02	20.86	38	31
CPT-4B 50'	216.8	0.0	19.20	26.75	39	28
CPT-4B 75'	73.6	0.0	12.54	14.89	38	32
CPT-4B 90'	485.6	0.0	41.72	54.67	38	29
CPT-4C 10'	1058.6	0.0	33.28	54.98	38	23
CPT-4C 25'	81.2	0.0	10.47	13.26	38	30
CPT-4C 50'	144.6	0.0	23.85	29.23	38	31
CPT-4C 75'	1251.6	0.0	72.13	94.52	38	29
CPT-4C 107'	479,2	0.0	46.56	68.05	38	26
CPT-4D 10'	28.6	0.0	5.42	10.06	13	7
CPT-4D 25'	28.6	0.0	6.70	7.92	13	11 :
CPT-4D 40'	28.6	0.0	8.46	11.00	13	10
CPT-4D 75'	61.0	0.0	14.97	19.46	13	10
CPT-4D 99'	49.0	0.0	14.68	21.20	13	9
CPT-4E 10'	448.0	0.0	14.85	33.19	38	17 '
CPT-4E 25'	60.4	0.0	6.96	10.17	38	26
CPT-4E 75'	515.8	0.0	28.49	38.66	38	28
CPT-4E 103'	135.6	0.0	17.26	24.30	38	27
CPT-4F 10'	333.4	0.0	14.47	28.13	35	18
CPT-4F 25'	365.0	0.0	20.96	31.89	35	23
CPT-4F 50'	224.0	0.0	24.54	33.03	35	26
CPT-4F 75'	125.6	0.0	17.11	24.95	35	24
CPT-4F 109'	45.6	0.0	11.19	17.80	35	22
CPT-4G 100'	186.8	0.0	37.21	44.19	38	32
CPT-4H 75'	396.2	0.0	51.37	59.15	38	33

SAMPLE POINT	MAXIMUM (all points)	MINIMUM (all points)	AVERAGE (all points)	AVERAGE (all positive points)	# SAMPLES (all points)	# SAMPLES (all positive points)
		(dii poilito)	(un points)	I (aii pooki vo pointo)	(un ponto)	Man positive points
CPT∔4J 25'	25.6	0.0	5.08	7.43	38	26
CPT-4L 50'	156.8	0.0	20.36	24.96	38	31
SG 86-4	62.9	0.0	7.03	12.34	86	49
SG 86-5	67.9	0.0	3.44	8.00	86	37
SG 86-6	307.0	0.0	4.63	24.59	85	16
SG 94-2	132.0	0.0	19.53	24.06	85	69
SG 94-4	71.2	0.0	10.10	11.45	85	75
SG 94-5	19.0	0.0	1.35	8.08	84	14
SG 94-7	22.2	0.0	1.18	6.28	85	16
SG C-1	20.6	0.0	2.10	4.58	198	91
SG E-2	407.0	0.0	12.78	27.95	199	91
SG E-3	17.5	0.0	1.22	3.90	195	61
SG N-1	4.8	0.3	2.55	2.55	2	. 2
SG N-2	112.8	0.0	2.52	5.74	196	86
SG N-3	95.0	0.0	2.80	5.11	188	103
SG N-5	204.8	0.0	2.50	6.58	200	76
SG N-6	1249.6	0.0	7.44	24.89	194	58
SG N-7	134.6	0.0	4.15	7.21	200	115_
SG N-8	10.0	10.0	10,00	10.00	1	1
SG N-9	517.2	0.0	7.37	12.12	199	121
SG S-1	0.6	0.6	0,60	0.60	1	1
SG W-1	291.2	0.0	2.92	7.27	197	79
SG W-3	2.4	2.4	2.40	2.40	1	1
SG W-5	50.2	0.0	2,93	4.66	194	122
W 10-9	3.9	0.0	0.08	2.10	84	3
W 10-15	0.1	0.0	0.00	0.10	84	1
W 10-16	0.0	0.0	0.00	0.00	84	0
W 10-17	0.2	0.0	0.00	0.20	84	1
W 10-18	0.2	0.0	0.00	0.20	83	1

BASELINE MONITORING STATISTICS - DECEMBER 1991 THROUGH DECEMBER 1993

Page3 of 6

SAMPLE POINT	MAXIMUM	MINIMUM	AVERAGE	AVERAGE	# SAMPLES	# SAMPLES
	(all points)	(all points)	(all points)	(all positive points)	(all points)	(all positive points)
W 10-71	0.0	0.0	0.00	0.00	78	0
W 10-81	0.0	0.0	0.00	0.00	78	0
W 11-1	2.3	0.0	0.04	1.23	84	3
W 11-27	0.1	0.0	0.00	0.10	84	1
W 11-28	0.1	0.0	0.00	0.10	83	1
W 14-12	3.8	0.0	0.06	2.57	84	2
W 14-51	0.1	0.0	0.00	0.10	83	1
W 15-4	49.8	0.0	1.76	8.30	80	17
W 15-5	401.0	0.0	14.33	39.08	1 <u>50</u>	55
W 15-6	1367.0	0.0	34.86	77.51	189	85
W 15-8	14.0	0.0	0.16	2,57	143	9
W 15-9	199,6	0.0	11.81	38.07	158	49
W 15-12	4.3	0.0	0.08	2.26	84	3
W 15-13	0.2	0.0	0.00	0.20	83	1
W 15-22	9.6	0.0	0.18	3.79	85	4
W 15-64	0.1	0.0	0.00	0.10	83	11
W 15-66	0.6	0.0	0.01	0,35	83	2
W 15-76	2.3	0.0	0.04	1.00	83	3
W 15-82	10000.0	0.0	383.96	651.07	195	115
W 15-84	1295.0	0.0	26.95	91.92	191	56
W 15-85	5737.0	0.0	142.12	349.84	160	65
W 15-86	21.8	0.0	0.23	2.56	144	13
W 15-95	10704.0	0.0	206,52	440.41	177	83
W 15-216	1271.0	0.0	40.18	123.06	49	16
VV 15-216 Lower Interval	588.0	0.0	39.68	105.23	61	23
VV 15-216 Upper Interval	621.0	0.0	42.09	. 142.62	61	18
W 15-217	3997.0	0.0	127.83	349.86	104	38
W 15-218	479.6	0.0	68.56	137.12	28	14
VV 15-218 Lower Interval	212.6	0.0	22.79	72.92	16	5

				<u> </u>		
SAMPLE POINT	MAXIMUM	MINIMUM	AVERAGE	AVERAGE	# SAMPLES	# SAMPLES
	(all points)	(all points)	(all points)	(all positive points)	(all points)	(all positive points)
W 15-218 Upper Interval	170.6	0.0	20.52	46.91	16	7
W 15-219 Lower Interval	31.8	0.0	3.48	26.10	15	2
W 15-219 Upper Interval	204.5	0.0	29.55	88.66	15	5
W 15-220 Lower Interval	114.8	0.0	16.99	63.70	15	4
W 15-220 Upper Interval	124.0	0.0	15.95	59.83	15	4
W 18-1	1018.0	0.0	16.58	42.23	191	75
W 18-2	806.0	0.0	22.24	47.72	191	89
W 18-5	0.0	0.0	0.00	0.00	2	0
W 18-6	1073.0	0.0	23.97	52.52	184	84
W 18-7	474.0	0.0	11.97	30.52	181	71
W 18-9	259.0	0.0	6.75	20.14	194	65
W 18-10	442.0	0.0	33.28	57'.06	36	21
W 18-11	188.4	0.0	4.32	13.53	194	6.2
W 18-12	199.0	0.0	5.60	18.45	191	58_
W 18-17	135.0	0.0	4.47	16.35	183	50
W 18-18	28.2	0.0	0.70	4.06	180	31
W 18-19	22.8	0.0	0.48	4.15	180	21
W 18-24	336.0	0.0	6.79	18.90	192	69
W 18-29	11.4	0.0	0.19	5.49	87	3
W 18-30	1.7	0.0	0.85	1.70	2	11
W 18-82	12.0	0.0	0.35	2.19	196	31
W 18-85	238.5	0.0	11.60	26.23	199	8B
W 18-86	170.0	0.0	7.90	22.98	195	67
W 18-87	70.0	0.0	2.93	8.74	209	70
W 18-88	5.3	0.0	0.13	1,07	194	23
W 18-89	212.0	0.0	3.30	13.98	. 195	46
W 18-93	114.0	0.0	1.38	9.93	194	27
W 18-94	117.7	0.0	2.04	12.93	196	31
W 18-95	169.4	_0.0	4.34	21.15	195	40_

~
H H
ᅹ
റ
S
ř
-QS
·
m
Z
ÈN-
I
ī`
265
6
(III
•
•
_
ᅍ
ro
Rev
•
_
0

SAMPLE POINT	MAXIMUM	MINIMUM	AVERAGE	AVERAGE	# SAMPLES	# SAMPLES
	(all points)	(all points)	(all points)	(all positive points)	(all points)	(all positive points)
			1			
W 18-96	246.5	0.0	8.62	34.11	186	47
W 18-97	17.5	0.0	3.56	6.18	33	19
W 18-98	39.0	0.0	1.22	4.90	184	46
W 18-99	56.0	0.0	0.63	3.37	171	32
W 18-152	119.6	0.0	7.36	19.04	88	34
W 18-153	1671.5	0.0	28.07	82.47	191	65
W 18-155	0.0	0.0	0.00	0.00	64	0
W 18-157	696.5	0.0	8.24	30.84	191	51
W 18-171	140.5	0.0	3.82	12.69	209	63
W 18-246	498.0	0.0	60.06	110.63	35	19
W 18-246 Lower Interval	450.0	0.0	21,20	43.71	101	49
W 18-246 Upper Interval	382.0	0.0	10.45	29.77	94	33
W 18-247	180.0	0.0	8.78	23.04	63	24
W 18-247 Lower Interval	114.0	0.0	10.14	38.01	. 60	16
W 18-247 Upper Interval	47.0	0.0	4.64	12.31	61	23
W 18-248	1532.0	0.0	23.76	107.70	136	30
W 18-249	120.0	0.0	9.34	19.41	133	64
VR-1 at Z-18	0.0	0.0	0.00	0.00	4	0
VR-2 at Z-18	1.8	0.0	0.45	1.80	4	1
VR-3 at Z-18	0.0	0.0	0.00	0.00	4	0
VR-4 at Z-18	0.0	0.0	0.00	0.00	4	0
VR-5 at Z-18	0,5	0.0	0.13	0.51	4	1
DAYTON & 16TH	0.0	0.0	0.00	0.00	1	0 .
FENCELINE S OF Z1A CRIB	0.3	0.3	0.30	0.30	1	1
NE FENCE CORNER	0.0	0.0	0.00	0.00	1	0
NE PERIMETER	0.0	0.0	0.00	0.00	1	0
NW FENCE CORNER	0.0	0.0	0.00	0.00	1	0 .
NW PERIMETER	0.0	0.0	0.00	0.00	1	0
S OF Z-9	0.0	0.0	0.00	0.00	1	0

SAMPLE POINT	MAXIMUM (all points)	MINIMUM (all points)	AVERAGE (all points)	AVERAGE (all positive points)	# SAMPLES (all points)	# SAMPLES (all positive points)
SE FENCE CORNER	0.4	0.4	0.37	0.37	1	1
SE PERIMETER	0.0	0.0	0.00	0.00	1	0
SW FENCE CORNER	0.0	0.0	0.00	0.00	1	0
SW PERIMETER	0.3	0.3	0.30	0.30	1	1
Z18 CRIB BETW V-R 1 & 2	0.0	0.0	0.00	0.00	1	0

WHC-SD-EN-TI-265, Rev. 0

APPENDIX B WELL CONSTRUCTION DATA

					•	1 .		SCREEN	OPEN ARE	A (OA) INF	ORMATIO	J .	T -	PERFO	RATION OP	EN AREA (DA) INFOR	MATION		BOTTOM	INFORM	IATION I	TOT	AI S
WELL	INT.	WELL	CASE	CASE	DEPTH	DEPTH	FEETE		TOTAL	*COR	Sq.in/ft	TOTAL	FEET B		TOTAL	*COR.	PERF.	Sq.in/ft	TOTAL	STATUS	CASE	TOTAL	INT.	WELL
No.	No.	TYPE	SIZE	TYPE*	то	TO		CASING	LENGTH	LENGTH	OPEN	SCREEN		CASING	LENGTH	LENGTH	PER	OPEN	PERF.	I	I.D.	вот.	OA	OA
					WATER	BOT	TOP	вот.	(FT.)	(FT.)	AREA	OA	TOP	BOT.	(FT)	(FT)	FOOT	AREA	OA			OA	(sq.in.)	(sq.in.)
W10-9	1	WATER	6-in	cs	214.12	225:00	202.00		18.00	12.12	53.00	642.36	N/A	N/A	N/A	N/A	NA	N/A	NA	SUB.	4.88	.	642.36	
W10-15	<u> </u>	WATER	4-in	SS	214.95	222.00	201.00	222.00	21.00	13.95	26.00			N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	362.70	642.36
W10-16	_ <u>-</u> -	WATER	4-in	SS	211.61	219.30	198.30	219.30	21.00	13.31	26.00	346.06		N/A	N/A	N/A	NA	N/A	N/A	CLOSED	N/A	0.00	345.06	362.70 346.06
W10-17	<u> </u>	WATER	4-in	SS	209.42	222.70		222.70	21.30	8.02	26.00	208.52	NA	NA	NA	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	208.52	208.52
W10-18	1	WATER	4-in	SS	208.61	221.10		221.10	21.30	8.81	26.00			N/A	NA	N/A	N/A	NA.	N/A	CLOSED	N/A	0.00	229.06	229.06
W19-1	1	WATER	6-in	CS	250.00	314.50		N/A	N/A	N/A	N/A	N/A	220.00	260.00	40.00	 	3.00	0.42	12.60		8.00	0.00	12.60	12.60
	2	WATER	8-in	CS	250.00	314.50	, _	NVA	N/A	N/A	N/A	N/A	270.00	311.00	41.00			0.70	0.00		N/A	0.00	0.00	N/A
W11-27	1	WATER	4-in	SS	224.67	233 60		233.60	20.40	11.47	26.00	298.22	N/A	N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	NA	0.00	293.22	298.22
W11-28	1	WATER	4-in	SS	232.25	244.90	224.00	244.90	20.90	8.25	26.00	214,50	N/A	N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	214.50	214.50
W14-12	1	WATER	4-in	SS	207.39	218.70		218.70	20.30	8.99	26.00	233.74		N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	NVA	0.00	233.74	233.74
W14-51	1	VAD.	6-in	CS		75:00		N/A	N/A	N/A	N/A	NVA	N/A	N/A	NA	N/A	N/A	N/A	NA	CLOSED	NVA	0.00	0.00	0.00
W15-4	1	WATER	8-in	CS	200.07	217.00		N/A	N/A	N/A	N/A	N/A	170.00	216.00	46.00			0.28		SUB.	8.00	0.00	8.40	8.40
W15-5	1	WATER	8-in	CS	203.46	340.00		N/A	N/A	N/A	N/A	N/A	173.00	217.00	44.00		1.00	0.14		SUB.	8.00	0.00	4.26	4.26
	2	WATER	8-in	CS	203.46	340.00		N/A	NA	N/A	N/A	N/A	480.00	524.00	123.00			0.56	0.00		N/A	0.00	0.00	
W15-6	. 1	WATER	8-in	cs	190.00	410.00		N/A	N/A	N/A	N/A	N/A	175.00	300.00	125.00	+		0.28		SUB.	8.00	0.00	3.36	3.36
	2	WATER	6-in	CS	190.00	410.00	N/A	N/A	N/A	N/A	NVA	N/A	307.00	408.00	101.00			0.28	0.00		N/A	0.00	0.00	
W15-8	1	WATER	8-in	cs	196.00	205.00		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	0.00	
W15-9	. 1	WATER	4-in	SS	190.00	194.00	N/A	N/A	N/A	N/A	N/A	N/A	186.00	189.00	3.00	3.00	2.00	0.28	0.84	SUB.	6.00	0.00	0.84	0.00 0.84
W15-12	1	WATER	6-in	cs	207.64	225.00	N/A	N/A	N/A	N/A	N/A	N/A	195.00	215.00	20.00	12.64	4.00	0.56	7.08	CLOSED	N/A	0.00	7.08	7.08
W15-13	1	WATER	6-in	CS	207.64	225.00	N/A	N/A	N/A	N/A	N/A	N/A	197.00	205.00	8.00	8.00		0.28	2.24	CLOSED	NA	0.00	2.24	3.35
	2	WATER	6-in	CS	207.64	225.00	N/A	N/A	N/A	N/A	N/A	N/A	205.00	225.00	20.00	2.64	3.00	0.42	1.11	CLOSED	N/A	0.00	1.11	N/A
W15-22	1	WATER	4-in	SS	206.46	219.60	198.50	219.80	21.30	7.96	26.00	206.96	N/A	N/A	N/A	N/A	N/A	N/A	NVA	CLOSED	N/A_	0.00	206.96	206.96
W15-64	1	VAD.	8-in	CS	N/A	189 00	N/A	N/A	N/A	N/A	N/A	N/A	0.00	150.00	150.00	150.00	2.00	0.28	42.00	CLOSED	N/A	0.00	42.00	42.00
W15-66	1_	VAD.	8-in	cs	N/A	7.3.00	N/A	NVA	NVA	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	0.00	0.00
W15-76	.1_	VAD.	8-in	cs	N/A	103 00	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	OPEN	8.00	50.27	50.27	50.27
W15-82	_1_	VAD.	8-in	cs		101.58		N/A	N/A	N/A	N/A	N/A	73.00	88.00	15.00	15.00	24.00	3.36	50.40	OPEN	8.00	50.27	100.67	100.67
W15-84	1	VAD.	8-in	CS		107.78		N/A	N/A	N/A	N/A	N/A	75.00	90.00	15.00	15.00	18.00	2.52	37.80	OPEN	8.00	50.27	88.07	88.07
W15-85	_1_	VAD.	8-in	CS	_	104.98		N/A	NVA	N/A	N/A	N/A	83.00	98.00	15.00	+	24.00	3.36		OPEN	8.00	50.27	100.67	100.67
W15-86	1	VAD.	4-in	cs	-	136.00		N/A	N/A	N/A	N/A	N/A	N/A	N/A	IN/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	0.00	0.00
W15-95	1	VAD.	8-in	CS		101.91	N/A	N/A	N/A	N/A	N/A	N/A	83.00	98.00	15.00			3.36	50.40	OPEN	8.00	50.27	100.67	100.67
W15-216		VAD.	4-in	SS	N/A	184.80	69.72	79.80	10.07	10.07	3.67	36.96		N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	NA	0.00	36.96	74.90
W45 247	- 4		4-in	SS		184.80	174.51	184.80	10.34	10.34	3.67	37.95	N/A	N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00		N/A
W15-217 W15-218	1	VAD.	4-in	SS	N/A N/A	121.00	106.00	121.00	13.20	13.20	3.67	48.44	N/A	N/A	IN/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	48,44	48.44
44 13-710	<u>1</u> _	VAD.	4-in 4-in	SS		195.30 195.30	98.50	113.50	25.20	25.20	3.67	92.48		NVA	IN/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	92.48	147.17
W15-219	1	VAD.	4-in 4-in	SS		195.30	180.40	195.30	14.90	14.90	3.67			N/A	IN/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	54.68	
44 12-519	1 2	VAD.	_	SS			87.20	102.20	15.00	15.00	3.67			N/A	IN/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	55.05	110.10
W15-220	'	VAD.	4-in 4-in	SS		212.00	121/22	182.20	15.00	15.00	3.67	55.05		N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	55.05	
** 13-220	2	VAD.	4-in	SS		201.00	80.00	95.10	15.10	15.10	3.67	55.42	_	N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	55.42	
W15-223	<u> </u>	VAD.	4-in 3.5-in	SS	N/A	201.00	155.00	170.00	15.00	15.00	3.67	55.05		N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	55.05	
W15-223 W18-1	'	WATER	3.5-in 6-in	CS		118.90 427.00	102.80 N/A	117.20 N/A		20.30	35.00	710.50		N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	710.50	710.50
77 10-1	- ! -	WATER	6-in	CS CS	209.00	427.00		N/A	N/A N/A	N/A N/A	N/A N/A	N/A N/A	195.00 238.00	236.00 240.00	41.00	+		0.84			8.00 N/A	0.00	11.76	11.76
	3	WATER	6-in	CS	209.00	427.00		N/A	N/A N/A	N/A	N/A	N/A	238,00	425.00	2.00 185.00						N/A N/A	0.00		_
W18-2	1	WATER	8-in	CS	210.00	254.00	205.00	254.50	N/A 49.50	0.00		0.00	200.00	425.00 278.00	185.00 78.00			0.84		CLOSED	N/A	0.00	0.00 45.78	N/A 45,78
W18-6	- -	WATER	. 6-iu	CS	DRY	203,68	205.00	254.50 N/A	49.50 N/A	N/A	N/A	N/A	190.00	249.00	78.00 59.00	+				FILLED IN	8.00	50.27	61.76	61.76
***************************************	2	WATER	6-in	CS	DRY	203.68	IN/A	N/A	N/A	N/A	N/A	IN/A	250.00	298.00	48.00			0.55	0.00		N/A	0.00	0.00	N/A
W18-7	1	WATER	6-in	CS	DRY	203,30	196,00	216.00	20.00	0.00	46.00	0.00	190.00	250.00	60.00			0.55		FILLED IN	N/A	21.99	33.16	33.16
		WATER	6-in	cs	DRY	203.30		N/A	N/A	N/A	N/A	N/A	270.00	298.00	28.00			0.84	0.00		N/A	0.00	0.00	
		1467171	, V 101			203.30	ביינון	I WA	I I WA	. 4473	1,82	Li WA	A/U.00	430.00	20.00	1 0.00	<u> </u>	U.04	1 0,00	J1#/71	1144	1 0.00	U.00	1.47

							Γ	SCREEN	OPEN ARE	A (OA) INFO	DRMATION	1		PERFOR	RATION OPI	EN AREA (C	A) INFOR	MATION		BOTTON	INFORM	IATION T	TOTA	ALS.
WELL	INT.	WELL	CASE	CASE	DEPTH	DEPTH	FEET 8	ELOW	TOTAL	*COR.	Sà.in/ft	TOTAL	FEETB		TOTAL	*COR.	PERF.	Sq.in/ft	TOTAL	STATUS	CASE	TOTAL	INT.	WELL
No.	No.	TYPE	SIZE	TYPE*	I то I	то	TOP OF	CASING	LENGTH	LENGTH	OPEN	SCREEN	TOP OF	CASING	LENGTH	LENGTH	PER	OPEN	PERF.		I.D.	BOT.	OA.	OA
				1	WATER	BOT.	TOP	BOT.	(FT.)	(FT.)	AREA	OA	TOP	вот.	(FT.)	(FT.)	FOOT	AREA	OA	İ	"-	OA	(sq.in.)	(sq.ln.)
V18-9	1	WATER	6-in	cs	208.00	217.00	182.00	212.00	30.00	0.00	26.00	0.00	180.00	189.00	9.00	9.00	4.00	0.56		CLOSED	N/A	0.00	5.04	12.88
	2	WATER	6-in	CS		217.00		N/A		N/A	N/A	N/A	190.00	200.00	10.00	10.00	4.00	0.56	5.60		NA	0.00	5.60	
	3	WATER	6-in	CS		217.00		N/A	N/A	N/A	N/A	N/A	200.00						2.24		N/A			_
W18-10	1	WATER	6-in	CS		214.30		N/A	N/A	N/A	N/A	N/A		218.00	18.00	8.00	2.00	0.28				0.00	2.24	
	2	WATER	6-in	cs		214.30	_	N/A	NA	N/A			100.00	130.00	30.00	30.00	30,00	4.20		CLOSED	N/A	0.00	126.00	1614.10
***************************************	3	WATER	6-in				1 2 2				N/A	N/A	150.00	180.00	30.00	*******	30.00	4.20		CLOSED	N/A	0.00	126.00	
W18-11		WATER		CS CS	1	214.30	188.00	220,00	32.00	25.70	53.00	1362.10	N/A	N/A		N/A	N/A	N/A	NA	CLOSED	N/A	0.00	1362 10	
W 1:0-11	<u> </u>		6-in	cs	DRY	188.60	190.00	220.00	30.00	0.00	35,00	0.00	180.00	200.00	20.00	0.00	4.00	0.56		FILLED IN	4.00	12.57	12.57	12.57
		WATER	6-in	cs			N/A	N/A	N/A	N/A	N/A	N/A	200.00	218.00	18.00	0.00	2.00	0.28	0.00	N/A	N/A	0.00	0.00	N/A
V18-12	1	WATER	6-in	cs	DRY	212.60	194.00	214,00	20.00	0.00	30.00	0.00	190.00	218.00	28.00	22.60	4.00	0.56	12.66	FILLED IN	N/A	15.71	28.37	28.37
V18-17	1	WATER	8-in	cs		218.20	189.40	219.40	20,00	0.00	29.00	0.00	200.00	220.00	20.00	5.00	4.00	0.56	2.80	CLOSED	N/A	0.00	2.80	2.80
	2	WATER	8-in	cs	205,00	218.20	N/A	N/A	N/A	N/A	N/A	N/A	220.00	250.00	30.00	0.00	2.00	0.28	0.00	N/A	N/A	0.00	0.00	N/A
V18-18	_1_	WATER	8-in	CS	188.00	201.64	183.00	204.00	21.00	0,00	29.00	0.00	185.00	210.00	25.00	3.00	4.00	0.56	. 1.68	CLOSED	N/A	0.00	1.68	1.68
	2	WATER	8-in	cs	188.00	201.64	N/A	N/A	NA	N/A	N/A	N/A	215.00	225.00	10.00	0.00	2.00	0.28	0.00	N/A	N/A	0.00	0.00	N/A
V18-19	1	WATER	6-in	cs	DRY	201.72	175.00	205.00	30.00	0.00	30.00	N/A	185.00	195.00	10.00	10.00	8.00	1.12	11.20	FILLED IN	N/A	0.00	11.20	11.20
	2	WATER	6-in	CS	DRY	201,72	NA	N/A	N/A	N/A	N/A	N/A	220.00	250.00	30.00	0.00	4.00	0.56	0.00		N/A	0.00	0.00	
V18-24	1	WATER	4-in	SS	220.15	240.00	205.50	235.50	30.00	14.65	45.00	659.25	N/A	N/A	NVA	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	659.25	659.25
	2	WATER	4-in	SS	220.15	240.00	230.00	240.00	10.00	0.00	82.00	0.00		NA	N/A	N/A	N/A	N/A	NVA	NA	N/A	0.00	0.00	
V18-29	1	WATER	4-In	SS		135.00	119.00	135.00		2.90	13.00	37.70		NA		NA	N/A	N/A	N/A	CLOSED	N/A	0:00	37.70	37.70
V1B-82	1	VAD.	6-in		N/A	146.00	N/A	N/A		N/A	N/A	N/A	N/A	N/A		N/A		N/A	N/A	OPEN	6.00	28.27	28.27	28.27
/18-85	1	VAD.	6-in		N/A	148.00		N/A		NA	NA	N/A	N/A					N/A	NA			•		
/18-86	1	VAD.	6-in		N/A	147.00		N/A		N/A	NVA	N/A		N/A		N/A				OPEN	6.00	28.27	28.27	28.27
/18-67	_ <u></u>	VAD.	6-in		N/A	148.00		N/A		N/A			N/A			N/A	N/A	N/A	N/A	OPEN	6.00	_	28.27	28.27
		VAD.			N/A						N/A	N/A	32.50	38.10	5.60	5.60	12.00	1.68	9.41	CLOSED	N/A	0.00	9.41	23.02
		****	6-in			148.00		N/A		N/A	N/A	N/A	64.70	67.90	3.20	3.20	12.00	1.68	5.38	N/A	N/A	0.00	5.38	
***	_3_	VAD.	6-in		N/A	148.00		N/A		N/A	N/A	N/A	124.40	129.30	4.90	4.90	12.00	1.68	8.23	N/A	N/A	0.00	8.23	N/A
V18-88	1_	VAD.	6-in		N/A	150.00		N/A		N/A	N/A	N/A	N/A	NVA	N/A	N/A	N/A	N/A	N/A	OPEN	6.00	28.27	28.27	28.27
V18-89	_1_	VAD.	6-in		N/A	150.00		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	OPEN	6.00	28.27	28.27	28.27
V1B-93	1	VAD.	6-in		N/A	138.00	N/A	N/A	N/A	N/A	N/A	N/A	63.00	77.00	14.00	14.00	24.00	3.36	47.04	CLOSED	N/A	0.00	47.04	47.04
V1B-94	_1_	VAD.	6-in	CS	N/A	83.00	N/A	N/A	N/A	N/A	N/A	N/A	68.00	78.00	10.00	10.00	24.00	3.36	33.60	CLOSED	6.00	0.00	33.60	28.27
V18-95	1	VAD.	6-in	CS	N/A	77.00	N/A	N/A	N/A	N/A	NA	N/A	N/A	NA	N/A	N/A	N/A	N/A	N/A	OPEN	6.00	28,27	28.27	28.27
V18-96	1	VAD.	2-in	SS	N/A	79.55	122.29	131.88	9.59	9.59	1.84	17.60	71.00	79.00	8.00	8.00	24.00	3.36	26.88	CLOSED	NA	0.00	26.88	26.88
V18-97	1	VAD.	6–in	CS	N/A	86.23	N/A	N/A	N/A	N/A	N/A	N/A	63.00	75.00	12.00	12.00	24.00	3.36	$\overline{}$	CLOSED	N/A	0.00	40.32	40.32
V18-98	1	VAD.	6-in	CS	N/A	75.30			N/A	NVA	NA	N/A	66.00	77.00	11.00	11.00	24.00	3.36	36.96		N/A	0.00	36.96	36.96
V1B-99	1	VAD.	6-in		N/A	132.00				N/A	N/A	NVA	93.00	103.00	10.00	10.00	24.00	3.36	33.60		NA	0.00	33.60	33.60
V1B-152	1	VAD.	8-in			118.00			N/A	N/A	N/A	N/A	N/A	N/A		N/A		N/A	N/A	OPEN	8.00		50.27	50.27
V18-153	1	VAD.	8-in		N/A	110.00				N/A	N/A	N/A	N/A					N/A	N/A	OPEN	8.00	50.27	50.27	50.27
V18-155	1	VAD.	10-in		N/A	17.00			N/A	NA	N/A	N/A	N/A	N/A		N/A		N/A	N/A	OPEN				
V18-157	- -	VAD.	8-in		N/A	110.00			N/A	N/A	N/A	N/A									10.00	78.54	78.54	78.54
V18-171	1	VAD.	8-in	_	N/A	131.00				N/A			N/A	N/A		N/A	N/A	N/A	N/A	OPEN	8.00	50.27	50.27	50.27
	2	VAD.	_					_			N/A	N/A	19.80	24.50	4.70		12.00	1.68	7.90		N/A	0.00	7.90	112.90
			8-in		N/A	131.00			N/A	N/A	N/A	N/A	56.00	76.00	20.00	20,00	24,00	3.36	67.20		N/A	0.00	67.20	
	3	VAD.	8-in		N/A	131.00			N/A	N/A	N/A	N/A	114,50	129.50	15,00	15.00	18.00	2.52	37.80		N/A	0.00	37.80	
/18-246		VAD.	4-in	SS		174.90	120.10	130.00	10.00	10.00	3.67	36.70		N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	36.70	73.40
	_2	VAD.	4-in		N/A	174.90	164.90	175.00	10.00	10.00	3.67	36,70		N/A	N/A	N/A	N/A	N/A	N/A	NVA	N/A	0.00	36.70	N/A
/18-247	_ 1	VAD.	4-in	_	N/A	172.00	119.00	129.00	10.00	10.00	3.67	36.70	N/A	N/A	N/A	N/A	N/A	N/A	N/A	CLOSED	N/A	0.00	36.70	73.40
	2	VAD.	4-in	SS	N/A	172.00	162.00	172.00	10.00	10.00	3.67	36.70	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0.00	36.70	N/A
					1											244	N/A	N/A	N/A	CLOCCO	1000			56.41
	1	VAD.	4-in	ss	N/A	138.55	123.00	138.00	15.37	15.37	3.67	56.41	N/A	N/A	N/A	N/A	NVA !	INVA I	INA	i Crosen	IN/A	0.001	56.41	
	1	VAD.	4-in	-	N/A N/A	138.55 136.68	123.00 121.00	138.00 136.00	15.37 14.98	15.37 14.98	3.67 3.67	56.41 54.98	_					N/A	N/A	CLOSED				
/18-248				SS						-			N/A	ΝA	N/A	N/A	N/A			CLOSED	N/A N/A	0.00	56.41 54.98 73.40	54.98 146.80

1	EACH	ITY INFORMA	ATION	COMMENTS
WELL	NAME	TYPE	DISTANCE	COMMENTS
No.	HOWE	11172	TO FACILIT	j
MU,	<i>i</i> *		(FT)	
W18-9	Z-18	Crib		6" telescope screen in a 6" case within perf. interval.
	Z-18	Crib	0	Plugged at 217
	Z-18	Crib	0	CASING BOTTOM IS OPEN BELOW THE PLUG
W18-10	Z-18	Crib		Perforated in 1994, 2 sets
	Z-18	Crib	2	
	Z-18	Crib	2	Wire wrap screen at bottom
W18-11	Z-18	Crib		4" Screen set at top of perf. interval, fitted in completely.
	Z-18	Crib	0	Vapor must pass through the perfs., screen and fill.
W18-12	Z-18	Crib	0	Telescoping screen in perf. Interval, partially filled in.
W18-17	Z-20	Trench		Tel. screen in perf. interval, plug at screen bottom.
	Z-20	Trench		Fifled In and plugged.
W18-18	Z-20	Trench		Assume 6" screen on packer, fill starts at bottom of screen
	Z-20	Trench		Bottom of case is plugged.
W18-19	Z-20	Trench		Screen in upper perf. Interval, lower interval filled in.
	Z-20	Trench		Case bottom is open but filled up to screen.
W18-24	Z-18	Crib	90	Two screens, one 4" and one 8".
	Z-18	Crib		Casing is 4" but the borehole is 8-16".
W18-29	Z-20	Trench		#5 slot equates to 13 sq.in., verified with Johnson Mfg.
W18-82	None	None	N/A	No perforations or screens. No record of any bottom plug.
W18-85	Z-1A	Tile Field	30	No perforations or screens. No record of any bottom plug.
W18-86	Z-1A	Tile Field	40	No perforations or screens. No record of any bottom plug.
W18-87	Z-1A	Tile Field	40	Three perforated intervals, Cement plug at bottom.
	Z-1A	Tile Field	40	<u> </u>
	Z-1A	Tile Field	40	
W18-88	Z-1A	Tile Field		No perforations or screens. No record of any bottom plug.
W18-89	Z-1A	Tile Field	50	No perforations or screens. No record of any bottom plug.
W18-93	Z-18	Crib	0	No perforations or screens. No record of any bottom plug.
W18-94	Z-18	Crib	3	No perforations or screens. No record of any bottom plug.
W18-95	Z-18	Crib		No perforations or screens. No record of any bottom plug.
W18-96	Z-18	Crib	0	
W18-97	Z-18	Crib		No perforations or screens. No record of any bottom plug.
W18-98	Z-18	Crib	3	
W18-99	None	None	N/A	No perforations or screens. No record of any bottom plug.
W18-152	Z-12	Crib		No perforations or screens, No record of any bottom plug.
W18-153	Z-12	Crib		No perforations or screens. No record of any bottom plug.
W18-155	Z-12	Crib Crib		No perforations or screens. No record of any bottom plug.
W18-157	Z-12			No perforations or screens. No record of any bottom plug.
W18-171	Z-1A	Tile Field	15	Three perforated intervals. Cement plug at bottom.
	Z-1A	Tile Field		
14440 040	Z-1A		70	
W18-246	Z-1A Z-1A	Tile Field		Louvered screen.
W18-247	Z-1A Z-18	Tile Field Crib		Louvered screen
1110-24/	Z-18 Z-18	Crib	70	Louvered screen
W18-248	Z-18 Z-1A	Tile Field	20	Louvered screen.
W18-248	Z-18	Спір		Louvered screen.
W18-249 W18-252	None	None	N/A	
** 10*202	None	None	N/A	Louvered screen. Louvered screen.
	IACHA	House	1.WA	Converse screen.

APPENDIX C CALCULATIONS USED TO DERIVE VADOSE OPEN AREA

I. VADOSE ZONE OPEN AREA CALCULATION ASSUMPTIONS:

- A. TOTAL SCREEN OPEN AREA = CORRECTED LENGTH (FT)* x Sq.in. OF OPEN AREA PER LINEAR FOOT.
- B. TOTAL PERF. OPEN AREA = CORRECTED LENGTH (FT)* x # OF PERFS PER FOOT X Sq.in. OF OPEN AREA PER P. C. TOTAL BOTTOM OPEN AREA = AREA OF APPLICABLE CIRCLE.
- D. INTERVAL TOTAL OPEN AREA (sq.in.) = THE SUM OF ALL THREE OPEN AREA TYPES IN THE APPLICABLE INTER
- E. BOREHOLE TOTAL OPEN AREA (sq.in.) = THE SUM OF ALL OPEN AREA INTERVALS IN THE APPLICABLE BOREH *Corrected length accounts for water and sand fill levels in each borehole.

II. SCREEN SPECIFICATIONS:

A. TYPE: CONTINUOUS WIRE WRAP, FROM JOHNSON WELL SCREENS.

Stainless Steel Vee-Wire TELESCOPE SIZE Screens.(1)

OPEN A	REA (SQ.IN) PER LINEAR	R FOOT	
PIPE	SLOT SIZE			
SIZE	0,005	0.010	0.020	
4"	20.00	35.00	13.00	
6"	30.00	53.00	N/A	
8.	29.00	52.00	N/A	

Stainless Steel Vee-Wire PIPE SIZE Screens.(1)

OPEN	AREA (SQ.IN	.) PER LINEA	R FOOT
PIPE		SLOT SIZE	
SIZE	0.005	0.010	0.020
3"	N/A	20.00	35.00
4"	13.00	26.00	45.00
5"	N/A	30.00	53.00
8"	N/A	33.00	60.00

B. TYPE: LOUVERED, FROM ROSCOE MOSS WELL SCREENS.(2) 4" DIA., .020 SLOT SIZE = 3.67 sq.in. PER LINEAR FOOT

III. PERFORATION SPECIFICATIONS:

A. TYPE: PERFHAWK, FROM HAWK INDUSTRIES, INC.(3)

WIDTH OF CUT:

.28125"

LENGTH OF CUT:

x.5"

0.140 ASSUMED OPEN AREA PER CUT (sq.in.).

B. TYPE: MILLS KNIFE, HOLE SIZE IS APPROX. THE SAME AS THE PERFHAWK. W15-64 IS THE ONLY DOCUMENTED WELL WITH THIS TYPE OF PERFORATION.

IV, BOTTOM OF CASING AREAS (SQ.IN.).

DIA.	AREA
3"	7.07
4"	12.57
6"	28.27
8"	50.27
10"	78.54

^{1.} Johnson Filtration Systems Inc., St. Paul, MN, Product Literature, 1991.

^{2.} Roscoe Moss Co., Los Angeles, CA, per telephone communication, 1993.

^{3.} Hawk Industries, Inc., Long Beach, CA, Product Literature, 1989.

APPENDIX D NONROUTINE FARFIELD MONITORING DATA

WELL NUMBER	DATE	OVM ppmv
299-W6-1	5/19/93	0
299-W6-2	5/19/93	o
299-W6-3	5/19/93	0
299-W6-4	5/19/93	0
299-W6-9	5/19/93	0
299-W6-10	5/19/93	Ö
299-W7-1	5/19/93	
299-W7-9	5/19/93	Ö
299-W7-10	5/19/93	0
299-W7-12	5/19/93	0
299-W8-1	5/19/93	0
299-W9-1	5/19/93	Ö
299-W10-1	5/19/93	Ö
299-W10-2	5/19/93	- 0
299-W10-4	5/19/93	0
299-W10-5	5/19/93	0
299-W10-8	5/19/93	0
299-W10-10	5/19/93	0
299-W10-11	5/19/93	
299-W10-12	5/19/93	0
299-W10-13	5/19/93	0
299-W10-14	5/19/93	0
299-W10-69	5/19/93	0
299-W10-70	5/19/93	0
299-W10-72	5/19/93	0
299-W10-73	5/19/93	<u> </u>
	5/19/93	0
299-W10-77	5/19/93	- 0
299-W10-78	5/19/93	0
299-W10-79	5/19/93	0
299-W10-169	5/19/93	0
299-W10-170	5/19/93	0
299-W11-7	5/19/93	0
299-W11-14	5/19/93	0
299-W11-15	5/19/93	0
299-W11-16	5/19/93	0
299-W11-17	5/19/93	0
299-W11-17 299-W11-18	5/19/93	0
299-W11-19	5/19/93	0
299-W11-20	5/19/93	0
299-W11-21	5/19/93	0
299-W11-23	5/19/93	- 0
299-W11-24	5/19/93	0
299-W11-31	5/19/93	-
299-W11-54	5/19/93	0
299-W11-55	5/19/93	- ;
299-W11-56	5/19/93	0
	5/19/93	0
	5/19/93 5/19/93	
200 W/44 64	5/19/93	
	5/19/93	0
	5/19/93	0
	5/19/93	0
	5/19/93	0
	5/19/93	0
299-W11-66	5/19/93	0

WELL NUMBER	DATE	OVM ppmv
299-W11-67	5/19/93	O O
299-W11-68	5/19/93	0
299-W11-69	5/19/93	0
299-W11-79	5/19/93	0
299-W11-80	5/19/93	0
299-W11-81	5/19/93	0
299-W14-52	5/12/93	0
299-W15-1	5/12/93	11
299-W15-7	5/12/93	Ö
299-W15-10	5/12/93	Ō
299-W15-14	5/13/93	Ö
000 MAINE 45	5/13/93	0
299-W15-16	5/13/93	0
299-W15-17	5/12/93	0
299-W15-17	5/13/93	0
299-W15-18	5/12/93	0
299-W15-18	5/13/93	. 0
299-W15-20	5/12/93	0
299-W15-23	5/12/93	0
299-W15-24	5/13/93	0
299-W15-52	5/12/93	0
299-W15-53	5/12/93	0
299-W15-54	5/12/93	0
299-W15-55	5/12/93	0
299-W15-56	5/12/93	0
299-W15-57	5/12/93	0
299-W15-59	5/12/93	0
299-W15-62	5/12/93	0
299-W15-63	5/12/93	0
299-W15-65	5/12/93	0
299-W15-80	5/12/93	0
299-W15-81	5/12/93	0
299-W15-151	5/13/93	0
299-W15-154	5/13/93	0
299-W15-209	5/12/93	0
299-W15-210 299-W15-210	5/12/93	
299-W15-211 299-W15-212	5/12/93	0
	5/12/93	0
299-W18-4	5/13/93	0
299-W18-5	5/13/93	0
299-W18-20	5/13/93	0
299-W18-21	5/13/93	0
299-W18-22	5/13/93	0
299-W18-23 299-W18-25	5/13/93 5/13/93	0
299-W18-26	5/13/93	0
299-W18-27	5/13/93	0
299-W18-28	5/13/93	0
299-W18-30	5/13/93	- 0
299-W18-31	5/13/93	ŏ
299-W18-32	5/13/93	0
299-W19-27	6/28/93	17
299-W19-91	6/28/93	13
699-39-79	5/19/93	0
699-40-80	5/19/93	0
		<u>-</u>

DISTRIBUTION SHEET						
То	From	From		Page 1 of 1		
Distribution		Environmental Restoration Field Sampling		Date 6/21/94		
Project Title/Work Order				EDT No. 600222		
Carbon Tetrachloride ERA Soi	1-Gas Baseline Moni	toring	<u>} </u>	ECN No. n/a		
Name	MSIN	Text With All Attach.	Text Only	Attach./ Appendix Only	EDT/ECN Only	
J. D. Fancher (10) W. S. Thompson W.H. Price W.J. Rohay G.C. Henckel T.W. Spicer S.A. Driggers J.N. Fisler B.G. Tuttle R.J. Schmitt M.G. Gardner S.H. Worley J.M. Jimenez M.S. Kowalski S.E. Kos K.J. Allwine G.I. Goldberg Central Files (2) Information Release(2)	N3-05 N3-05 N3-05 H6-06 H6-04 T1-95 H6-04 N3-06 N3-06 N3-06 N3-06 N3-06 N3-06 H6-06 K6-11 A5-19 L8-04 H4-17	X X X X X X X X X X X X X X X X X X X				

THIS PAGE INTENTIONALLY LEFT BLANK